History 2016/7/15 V1.0 Initial Version 2016/7/25 V1.0 Final Version 2017/3/13 V1.1 From PADs to Capture, Fix the bugs in V1.0 V1.0.2 From V1.1, Fix the bugs in V1.0 2017/5/1 2017/5/24 V1.0.3 1. U10: Load switch TPS22860DBVR replace LDO TPS73101, VCC 3V replace VCC WIFI 3V3, delete C48, remove V9, V10; 2. U11: LM3671MF 600mA pin to pin replace TPS62200DBV 300mA; 3. change R34, R35 to 0ohm; 4. change L4 4.7uH to 2.2uH(LPO3310-222MLC) 5. U5: Connect WDO to PA4(NMI b) Note: 1. DNP - Do not place. <Title> Document Number Rev Tuesday, June 13, 2017





