ISLAND MOTORCYCLE COMPANY

Isaac Douglas Lea 1-2315 Cook St Victoria, BC V8T 3R3

Repair Order

Invoice

Doc Number: 314016 Service Writer: Scott Tominski Date Printed: 08/06/2024 **Date Promised: 11/23/2023** Cashier: Scott Tominski Cashier Date: 11/25/2023

Customer Information

Home Phone: 250-507-9010 Cell Phone: 250-507-9010

Email: isaaclea123@gmail.com

Summary

Approve	Decline	Unit	Job	Job Total
$\overline{\vee}$		2023 Triumph Tiger 900 Rally Pro	* TRI Tiger 900 10K Service Checklist **DO NOT CHANGE ENGINE OIL OR	\$262.50
		2023 Triumph Tiger 900 Rally Pro	* TRI Tiger 900 Rally Pro Replace LH Fork Seal, Fluid & Components	\$387.42
			Job Subtotal:	\$649.92
			Misc:	\$70.00
			Job Parts Subtotal:	\$124.92
			Job Labor Subtotal:	\$525.00
			PST - 1001-1272 - 7.00%:	\$50.40
			GST - 12662 6357RT0001 - 5.00%:	\$36.00
			Total:	\$806.32
			Less Deposits:	\$0.00
			Visa:	(\$806.32)
			Total Due:	\$0.00

THANK	YOU	FOR	YOUR	BUSINE	SSII

** VEHICLES NOT PICKED UP WITHIN 5 DAYS OF NOTIFICATION OF WORK COMPLETION WILL BE SUBJECT TO A \$25.00 PER DAY STORAGE FEE. **

WE DO NOT RETAIN TAKE OFF PARTS UNLESS REQUESTED BY CUSTOMER. PARTS MUST BE PICKED UP WITHIN 7 DAYS OR THEY WILL BE DISPOSED OF.__ _ INITIAL PLEASE

NO RETURNS ON ELECTRICAL PARTS

DUE TO THE FACTORY COATING ON ALL NEW TIRES. A 'BREAK-IN' PERIOD IS REQUIRED BEFORE TIRES WILL DELIVER FULL TRACTION. ISLAND MOTORCYCLE COMPANY ACCEPTS NO LIABILITY FOR ACCIDENTS CAUSED BY IMPROPER USE DURING INITIAL WEAR PERIOD.

"I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH AND THE USE OF THE MATERIAL NECESSARY TO THE COMPLETION OF SAID REPAIR WORK. TO THE EXTENT PERMITTED BY LAW, WE ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO THE VEHICLE OR ARTIFACTS LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY THE UNAVAILABILITY OF PARTS OR DELAYS IN THE SHIPMENT OF PARTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND YOUR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING OR INSPECTION, "

GST # 126626357 RT0001 PST #1001-1272

Signature:	

Detail

Plate:

Unit

2023 Triumph Tiger 900 Rally Pro Tiger 900

Rally Pro

Color:Sandstorm

VIN/Serial No:SMTE67DF9PTBC1226

Odom/Hrs In:9,921

Out:9,926

TRI Tiger 900 10K Service Checklist **DO NOT CHANGE ENGINE OIL OR FILTER

Description:Tiger 900 10K Service Checklist **DO NOT CHANGE ENGINE OIL OR FILTER

**Customer installed aftermarket (fix) for LH joy stick on LH switch block, only operates up and left/.

Resolution:

10k service checklist **no oil/filter change as per customer**

Oil was low - topped up. Battery tested - good. Brake fluid level - good.

Brake pads - good, above 50% both front & rear.

Tire tread depth - lots of tread.

Tires set 34psi / 42psi.

Chain cleaned and lubed.

--> chain starting to stretch, still okay though.

--> chain slack way too loose and adjuster locking nuts not tightened.

Chain slack set to 30mm freeplay and adjusters torqued.

Coolant level low, topped up.

Throttle bodies balanced.

Instruments, engine ecm, and connectivity updated.

Autoscan unit.

Test ride - good.

Parts

Part #	Qty	Description	Price	Discount	Total
T1218001	0.00	OIL FILTER	\$20.99	\$0.00	\$0.00
153307-L	0.00	OIL,4T,SAE,15W50,FULL,SYN	\$18.99	\$0.00	\$0.00
T3558989	0.00	WASHER, SEALING	\$1.99	\$0.00	\$0.00

Parts Subtotal \$0.00

Labor

L	Description	rechnician	TOLAI
*	TRI Tiger 900 10K Service Checklist	Tony Ebbs-Canavan	\$262.50

Labor Subtotal

\$262.50

Job Subtotal Approve: ☑ \$262.50

Decline:

*TRI Tiger 900 Rally Pro Replace LH Fork Seal, Fluid & Components

Description:Tiger 900 Rally Pro Replace LH Fork Seal, Fluid & Components

Resolution:remove front end

remove front fork

disassemble, clean and reassemble fork replaced all fork components and fluid

reattached fork

torqued all components to spec headstock bearings felt good

Parts

Part #	Qty	Description	Price	Discount	Total
T2043354	1.00	DUST SEAL	\$13.99	\$0.00	\$13.99
T2046143	1.00	OIL SEAL	\$23.99	\$0.00	\$23.99
T2042907	1.00	SEALING WASHER	\$4.99	\$0.00	\$4.99
T2048748	1.00	SLIDE BUSH	\$11.99	\$0.00	\$11.99
T2041690	1.00	OIL SEAL STOPPE	\$26.99	\$0.00	\$26.99
T2048746	1.00	GUIDE BUSH	\$12.99	\$0.00	\$12.99
T2046138	1.00	O RING	\$3.99	\$0.00	\$3.99
153368	1.00	FORK OIL SAE 10W MEDIUM 1L LIQ	\$25.99	\$0.00	\$25.99

Parts Subtotal

\$124.92

_a	bo	r

Description	Technician	Total
Tiger 900 Rally Pro Replace Fork Seal, Fluid & Components	Tony Ebbs-Canavan	\$262.50
	Labor Subtotal	\$262.50

Job Subtotal	\$387.42
Approve: ☑	Decline: □
All Jobs Subtotal:	\$649.92
Shop Supplies:	\$70.00
PST - 1001-1272 - 7.00%:	\$50.40
GST - 12662 6357RT0001 - 5.00%:	\$36.00
Total:	\$806.32
Less Deposits:	\$0.00
Visa:	(\$806.32)
Total Due:	\$0.00