#### V 1.06

# QMOT QSH4218 MANUAL



QSH-4218 -35-10-027

42mm 1A, 0.27Nm



-41-10-035

42mm 1A, 0.35Nm



-51-10-049

42mm 1A, 0.49Nm

-47-28-040

42mm 2.8A, 0.40Nm

TRINAMIC Motion Control GmbH & Co. KG Hamburg, Germany

www.trinamic.com



# **Table of Contents**

1	Life support policy	3
2	Features	4
3	Order codes	5
4	Mechanical dimensions	6
	4.1 Lead wire configuration	6
	4.2 Dimensions	6
5	Torque figures	7
	5.1 Motor QSH4218-35-10-027	7
	5.2 Motor QSH4218-41-10-035	7
	5.3 Motor QSH4218-51-10-049	8
	5.4 Motor QSH4218-47-28-040	
6	Considerations for operation	9
	6.1 Choosing the best fitting motor for an application	
	6.1.1 Determining the maximum torque required by your application	
	6.2 Motor Current Setting	
	6.2.1 Choosing the optimum current setting	
	6.2.2 Choosing the standby current	
	6.3 Motor Driver Supply Voltage	
	6.3.1 Determining if the given driver voltage is sufficient	
	6.4 Back EMF (BEMF)	
	6.5 Choosing the Commutation Scheme	
	6.5.1 Fullstepping	
	6.5.1.1 Avoiding motor resonance in fullstep operation	
7	Revision history	
′	7.1 Document revision	
Fig Fig	ist of Figures gure 4.1: Lead wire configurationgure 4.2: Dimensions (all values in mm)gure 5.1: QSH4218-35-10-027 speed vs. torque characteristics	6
_	gure 5.2: QSH4218-41-10-035 speed vs. torque characteristics	
	gure 5.3: QSH4218-51-10-049 speed vs. torque characteristics	
_	gure 5.4: QSH4218-47-28-040 speed vs. torque characteristics	
Ta Ta	ist of Tables ble 2.1: Motor technical datable 4.1: Lead wire configuration	6
	ble 6.1: Motor current settings	
	ble 6.2: Driver supply voltage considerations	
	ble 6.3: Comparing microstepping and fullstepping	12
Tal	hle 7.1. Document revision	12

# 1 Life support policy

TRINAMIC Motion Control GmbH & Co. KG does not authorize or warrant any of its products for use in life support systems, without the specific written consent of TRINAMIC Motion Control GmbH & Co. KG.

Life support systems are equipment intended to support or sustain life, and whose failure to perform, when properly used in accordance with instructions provided, can be reasonably expected to result in personal injury or death.

© TRINAMIC Motion Control GmbH & Co. KG 2011

Information given in this data sheet is believed to be accurate and reliable. However neither responsibility is assumed for the consequences of its use nor for any infringement of patents or other rights of third parties, which may result from its use.

Specifications are subject to change without notice.



# 2 Features

These two phase hybrid stepper motors are optimized for microstepping and give a good fit to the TRINAMIC family of motor controllers and drivers. They are all used in the 42mm PANdrive™ family. The QSH4218-35-10-027, QSH4218-41-10-035 and QSH4218-51-10-049 are motors with 1A RMS coil current. The QSH4218-47-28-40 is different: It is designed for 2.8A RMS coil current to provide maximum torque at high velocities.

#### Characteristics of all QSH4218 motors:

- NEMA 17 mounting configuration
- flange max. 42.3mm \* 42.3mm
- step angle: 1.8°
- optimized for microstep operation
- optimum fit for TMC236/TMC246 based driver circuits
- 4 wire connection
- CE approved

#### Special characteristics of the QSH4218-47-28-40 motor:

- optimized for 2.8A RMS coil current to provide maximum torque at high velocities
- 0.25Nm torque at 1200 RPM with a 24V supply
- holding torque 0.40Nm

Charifications	Units	QSH4218			
Specifications	Units	-35-10-027	-41-10-035	-51-10-049	-47-28-040
Rated Voltage	٧	5.3	4.5	5.0	1.4
Rated Phase Current	Α	1.0	1.0	1.0	2.8
Phase Resistance at 20°C	Ω	5.3	4.5	5.0	0.5 ± 10%
Phase Inductance (typ.)	mH	6.6	7.5	8.0	0.6 ± 20%
Holding Torque (tun)	Ncm	27	35	49	40
Holding Torque (typ.)	oz in	38	50	69	56.3
Detent Torque	mNm	22	25	28	
Rotor Inertia	g cm²	35	54	68	68
Weight (Mass)	Kg	0.22	0.28	0.35	0.35
Insulation Class		В	В	В	В
Dielectic Strength (for one minute)	VAC	500	500	500	500
Connection Wires	N°	4	4	4	4
Step Angle	0	1.8	1.8	1.8	1.8
Step angle Accuracy (max.)	%	5	5	5	5
Flange Size (max.)	mm	42.3	42.3	42.3	42.3
Motor Length (max.)	mm	33.5	38	47	47
Rear shaft hole depth	mm	5.0	5.0	5.0	5.0
Rear shaft hole diameter	mm	3.0	3.0	3.0	3.0
Axis Diameter	mm	5.0	5.0	5.0	5.0
Axis Length (typ.)	mm	24	24	24	24
Axis D-cut (0.5mm depth)	mm	20	20	20	20
Maximum Radial Force	N.	28	28	28	20
(20 mm from front flange)	N				28
Maximum Axial Force	N	10	10	10	10
Ambient temperature	°C	-20+50	-20+50	-20+50	-20+50

Table 2.1: Motor technical data

# 3 Order codes

The length of the motor is specified without the length of the axis. For the total length of the product add 24mm.

Order code Description		Dimensions (mm)
QSH4218-35-10-027	QMot stepper motor 42mm, 1A, 0.27Nm	42.3 X 42.3 X 33,5
QSH4218-41-10-035	QMot stepper motor 42mm, 1A, 0.35Nm	42.3 x 42.3 x 38
QSH4218-51-10-049	QMot stepper motor 42mm, 1A, 0.49Nm	42.3 X 42.3 X 47
QSH4218-47-28-040	QMot stepper motor 42mm, 2.8A, 0.40Nm	42.3 X 42.3 X 47

Tabelle 3.1: Order codes

# 4 Mechanical dimensions

# 4.1 Lead wire configuration

Cable type	Coil	Function
Black	Α	Motor coil A pin 1
Green	Α-	Motor coil A pin 2
Red	В	Motor coil B pin 1
Blue	B-	Motor coil B pin 2

Table 4.1: Lead wire configuration




Figure 4.1: Lead wire configuration

### 4.2 Dimensions




Figure 4.2: Dimensions (all values in mm)

4xM3 Deep 4.5

# 5 Torque figures

The torque figures detail motor torque characteristics for half step operation in order to allow simple comparison. For half step operation there are always a number of resonance points (with less torque) which are not depicted. These will be minimized by microstep operation in most applications.

### 5.1 Motor QSH4218-35-10-027

Testing conditions: driver supply voltage +24V DC, coil current 1.0A RMS, half step operation




Figure 5.1: QSH4218-35-10-027 speed vs. torque characteristics

# 5.2 Motor QSH4218-41-10-035

Testing conditions: driver supply voltage +24V DC, coil current 1.0A RMS, half step operation




Figure 5.2: QSH4218-41-10-035 speed vs. torque characteristics

# 5.3 Motor QSH4218-51-10-049

Testing conditions: driver supply voltage +24V DC, coil current 1.0A RMS, half step operation




Figure 5.3: QSH4218-51-10-049 speed vs. torque characteristics

## 5.4 Motor QSH4218-47-28-040

Testing conditions: driver supply voltage: +24V DC, coil current: 2.8A RMS, half step operation




Figure 5.4: QSH4218-47-28-040 speed vs. torque characteristics

# 6 Considerations for operation

The following chapters try to help you to correctly set the key operation parameters in order to get a stable system.

### 6.1 Choosing the best fitting motor for an application

For an optimum solution it is important to fit the motor to the application and to choose the best mode of operation. The key parameters are the desired motor torque and velocity. While the motor holding torque describes the torque at stand-still, and gives a good indication for comparing different motors, it is not the key parameter for the best fitting motor. The required torque is a result of static load on the motor, dynamic loads which occur during acceleration/deceleration and loads due to friction. In most applications the load at maximum desired motor velocity is most critical, because of the reduction of motor torque at higher velocity. While the required velocity generally is well known, the required torque often is only roughly known. Generally, longer motors and motors with a larger diameter deliver a higher torque. But, using the same driver voltage for the motor, the larger motor earlier looses torque when increasing motor velocity. This means, that for a high torque at a high motor velocity, the smaller motor might be the fitting solution. Please refer to the torque vs. velocity diagram to determine the best fitting motor, which delivers enough torque at the desired velocities.

#### 6.1.1 Determining the maximum torque required by your application

Just try a motor with a torque 30-50% above the application's maximum requirement. Take into consideration worst case conditions, i.e. minimum driver supply voltage and minimum driver current, maximum or minimum environment temperature (whichever is worse) and maximum friction of mechanics. Now, consider that you want to be on the safe side, and add some 10 percent safety margin to take into account for unknown degradation of mechanics and motor. Therefore try to get a feeling for the motor reliability at slightly increased load, especially at maximum velocity. That is also a good test to check the operation at a velocity a little higher than the maximum application velocity.

### 6.2 Motor Current Setting

Basically, the motor torque is proportional to the motor current, as long as the current stays at a reasonable level. At the same time, the power consumption of the motor (and driver) is proportional to the square of the motor current. Optimally, the motor should be chosen to bring the required performance at the rated motor current. For a short time, the motor current may be raised above this level in order to get increased torque, but care has to be taken in order not to exceed the maximum coil temperature of 130°C respectively a continuous motor operation temperature of 90°C.

Percentage of rated current	Percentage of motor torque	Percentage of static motor power dissipation	Comment
150%	≤150%	225%	Limit operation to a few seconds
125%	125%	156%	Operation possible for a limited time
100%	100%	100% = 2 * I <sub>RMS RATED</sub> * R <sub>COIL</sub>	Normal operation
85%	85%	72%	Normal operation
75%	75%	56%	Normal operation
50%	50%	25%	Reduced microstep exactness due to torque reducing in the magnitude of detent torque
38%	38%	14%	-"-
25%	25%	6%	-"-
0%	see detent torque	0%	Motor might loose position if the application's friction is too low

Table 6.1: Motor current settings

#### 6.2.1 Choosing the optimum current setting

Generally, you choose the motor in order to give the desired performance at nominal current. For short time operation, you might want to increase the motor current to get a higher torque than specified for the motor. In a hot environment, you might want to work with a reduced motor current in order to reduce motor self heating.

The Trinamic drivers allow setting the motor current for up to three conditions:

- Stand still (choose a low current)
- Nominal operation (nominal current)
- High acceleration (if increased torque is required: You may choose a current above the nominal setting, but be aware, that the mean power dissipation shall not exceed the motors nominal rating)

#### 6.2.2 Choosing the standby current

Most applications do not need much torque during motor standstill. You should always reduce the motor current during standstill. This reduces power dissipation and heat generation. Depending on your application, you typically at least can half power dissipation. There are several aspects why this is possible: In standstill, motor torque is higher than at any other velocity. Thus, you do not need the full current even with a static load! Your application might need no torque at all, but you might need to keep the exact microstep position: Try how low you can go in your application. If the microstep position exactness does not matter for the time of standstill, you might even reduce the motor current to zero, provided that there is no static load on the motor and enough friction in order to avoid complete position loss.

### 6.3 Motor Driver Supply Voltage

The driver supply voltage in many applications cannot be chosen freely, because other components have a fixed supply voltage of e.g. 24V DC. If you have the possibility to choose the driver supply voltage, please refer to the driver data sheet and consider that a higher voltage means a higher torque at higher velocity. The motor torque diagrams are measured for a given supply voltage. You typically can scale the velocity axis (steps/sec) proportionally to the supply voltage to adapt the curve, e.g. if the curve is measured for 48V and you consider operation at 24V, half all values on the x-Axis to get an idea of the motor performance.

For a chopper driver, consider the following corner values for the driver supply voltage (motor voltage). The table is based on the nominal motor voltage, which normally just has a theoretical background in order to determine the resistive loss in the motor.

# Comment on the nominal motor voltage: (Please refer to motor technical data table.)

$$U_{COIL\_NOM} = I_{RMS\_RATED} * R_{COIL}$$

Parameter	Value	Comment
Minimum driver	2 * U <sub>COIL_NOM</sub>	Very limited motor velocity. Only slow movement without
supply voltage	_	torque reduction. Chopper noise might become audible.
Optimum driver	≥ 4 * U <sub>COIL NOM</sub>	Choose the best fitting voltage in this range using the motor
supply voltage	and	torque curve and the driver data. You can scale the torque
	≤ 22 * U <sub>COTL NOM</sub>	curve proportionally to the actual driver supply voltage.
Maximum rated	25 * U <sub>COIL_NOM</sub>	When exceeding this value, the magnetic switching losses in
driver supply	_	the motor reach a relevant magnitude and the motor might
voltage		get too hot at nominal current. Thus there is no benefit in
		further raising the voltage.

Table 6.2: Driver supply voltage considerations

#### 6.3.1 Determining if the given driver voltage is sufficient

Try to brake the motor and listen to it at different velocities. Does the sound of the motor get raucous or harsh when exceeding some velocity? Then the motor gets into a resonance area. The reason is that the motor back-EMF voltage reaches the supply voltage. Thus, the driver cannot bring the full current into the motor any more. This is typically a sign, that the motor velocity should not be further increased, because resonances and reduced current affect motor torque.

#### Measure the motor coil current at maximum desired velocity

For microstepping: If the waveform is still basically sinusoidal, the motor driver supply voltage is

sufficient.

For Fullstepping: If the motor current still reaches a constant plateau, the driver voltage is

sufficient.

If you determine, that the voltage is not sufficient, you could either increase the voltage or reduce the current (and thus torque).

#### 6.4 Back EMF (BEMF)

Within SI units, the numeric value of the BEMF constant has the same numeric value as the numeric value of the torque constant. For example, a motor with a torque constant of 1 Nm/A would have a BEMF constant of 1V/rad/s. Turning such a motor with 1 rps (1 rps = 1 revolution per second = 6.28 rad/s) generates a BEMF voltage of 6.28V.

#### The Back EMF constant can be calculated as:

$$U_{BEMF} \left[ \frac{V}{rad / s} \right] = \frac{MotorHoldingTorque[Nm]}{2 \cdot I_{NOM}[A]}$$

The voltage is valid as RMS voltage per coil, thus the nominal current  $I_{NOM}$  is multiplied by 2 in this formula, since the nominal current assumes a full step position, with two coils switched on. The torque is in unit [Nm] where 1Nm = 100cNm = 100cNm.

One can easily measure the BEMF constant of a two phase stepper motor with a (digital) scope. One just has to measure the voltage of one coil (one phase) when turning the axis of the motor manually. With this, one gets a voltage (amplitude) and a frequency of a periodic voltage signal (sine wave). The full step frequency is 4 times the frequency the measured sine wave.

### 6.5 Choosing the Commutation Scheme

While the motor performance curves are depicted for fullstepping and halfstepping, most modern drivers provide a microstepping scheme. Microstepping uses a discrete sine and a cosine wave to drive both coils of the motor, and gives a very smooth motor behavior as well as an increased position resolution. The amplitude of the waves is 1.41 times the nominal motor current, while the RMS values equal the nominal motor current. The stepper motor does not make loud steps any more – it turns smoothly! Therefore, 16 microsteps or more are recommended for a smooth operation and the avoidance of resonances. To operate the motor at fullstepping, some considerations should be taken into account.

<b>Driver Scheme</b>	Resolution	Velocity range	Torque	Comments
Fullstepping	200 steps per	Low to very high.	Full torque if dam-	Audible noise
	rotation	Skip resonance	pener used,	especially at low
		areas in low to	otherwise reduced	velocities
		medium velocity	torque in resonance	
		range.	area	
Halfstepping	200 steps per	Low to very high.	Full torque if dam-	Audible noise
	rotation * 2	Skip resonance	pener used,	especially at low
		areas in low to me-	otherwise reduced	velocities
		dium velocity	torque in resonance	
		range.	area	
Microstepping	200 * (number of	Low to high.	Reduced torque at	Low noise, smooth
	microsteps) per		very high velocity	motor behavior
	rotation			
Mixed: Micro-	200 * (number of	Low to very high.	Full torque	At high velocities,
stepping and	microsteps) per			there is no audible
fullstepping for	rotation			difference for full-
high velocities				stepping

Table 6.3: Comparing microstepping and fullstepping

Microstepping gives the best performance for most applications and can be considered as state-of-the art. However, fullstepping allows some ten percent higher motor velocities, when compared to microstepping. A combination of microstepping at low and medium velocities and fullstepping at high velocities gives best performance at all velocities and is most universal. Most Trinamic driver modules support all three modes.

#### 6.5.1 Fullstepping

When operating the motor in fullstep, resonances may occur. The resonance frequencies depend on the motor load. When the motor gets into a resonance area, it even might not turn anymore! Thus you should avoid resonance frequencies.

#### 6.5.1.1 Avoiding motor resonance in fullstep operation

Do not operate the motor at resonance velocities for extended periods of time. Use a reasonably high acceleration in order to accelerate to a resonance-free velocity. This avoids the build-up of resonances. When resonances occur at very high velocities, try reducing the current setting.

A resonance dampener might be required, if the resonance frequencies cannot be skipped.

# 7 Revision history

## 7.1 Document revision

Version	Date	Author	Description
1.00		HC	Initial Release
1.01	2007-JUN-20	HC	Chapter Fehler! Verweisquelle konnte nicht gefunden
			werden. optimum motor settings added
1.02	2007-JUL-11	HC	Chapter 5: motor codes corrected
1.03	2007-NOV-13	HC	Chapter 6.4 Back EMF (BEMF) added
1.04	2009-APR-01	GE	Max. operating voltage added
1.05	2009-JUN-20	SD	QSH4218-47-28-040 and order codes added, dimensions
			and torque figures reconditioned, further minor changes
1.06	2011-APR-12	SD	Front page new, figure in paragraph 4.2 (dimensions)
			completed, minor changes

Table 7.1: Document revision