

WORKERS' COMPENSATION FIELD SURVEY & RISK ASSESSMENT

Policyholder:	Genesis Fabricators Inc	Survey Date:	2024-05-22
Parent Company:	Genesis Corp	Safety Inspector:	Insp. David Miller
Policy Period:	2024-04-01 to 2025-03-31	Primary Equipment:	Shear-Max Cutters

EXECUTIVE SUMMARY & OPERATIONAL OBSERVATIONS

Genesis Fabricators suffers from a failure to control liquid spills. Puddles of cooling lubricant and thick hydraulic oil are leaking from the main cutter onto the concrete walking floor, creating highly slick walkways. Safety signage is present, but active cleanup of slippery pooling fluid is inconsistent, raising severe slip and fall hazard exposures.

DETAILED SAFETY AREA RISK ASSESSMENT

The following table lists the assessments and safety control levels recorded for each of the eight core Workers' Compensation hazard mitigation areas. These findings are used to calculate the account's historical and loss-weighted risk profiles.

Hazard Mitigation Area	Qualitative Assessment Rating
Lifting (Industrial Ergonomics)	ADEQUATE
Lacerations/Cut Safety	LIMITED/INCONSISTENT
Material Loading/Unloading & Securement	ADEQUATE
Overhead Lifting Equipment	ADEQUATE
Machine Guarding & Electrical Systems Safety (LOTO)	ADEQUATE
Occupational Disease & Illness	ADEQUATE
Walking/Working Surfaces	LIMITED/INCONSISTENT
Elevated Work Surfaces	NOT APPLICABLE