

WORKERS' COMPENSATION FIELD SURVEY & RISK ASSESSMENT

Policyholder:	Ironclad Manufacturing Corp	Survey Date:	2024-11-05
Parent Company:	Independent	Safety Inspector:	Marcus Vance
Policy Period:	2024-06-01 to 2025-05-31	Primary Equipment:	Hydraulic Press Model

EXECUTIVE SUMMARY & OPERATIONAL OBSERVATIONS

Ironclad Manufacturing displays severe structural safety neglect. Machine guards on the main HydroPress-9000 are frequently bypassed during quick tool changes on the stamping line. Exposed electrical wires are visible on the side of the stamping presses. Ergonomics is poor, with manual handling of sheet metal causing frequent worker complaints and historical cut injuries due to inadequate personal protective equipment.

DETAILED SAFETY AREA RISK ASSESSMENT

The following table lists the assessments and safety control levels recorded for each of the eight core Workers' Compensation hazard mitigation areas. These findings are used to calculate the account's historical and loss-weighted risk profiles.

Hazard Mitigation Area	Qualitative Assessment Rating
Lifting (Industrial Ergonomics)	INADEQUATE
Lacerations/Cut Safety	INADEQUATE
Material Loading/Unloading & Securement	ADEQUATE
Overhead Lifting Equipment	LIMITED/INCONSISTENT
Machine Guarding & Electrical Systems Safety (LOTO)	INADEQUATE
Occupational Disease & Illness	ADEQUATE
Walking/Working Surfaces	LIMITED/INCONSISTENT
Elevated Work Surfaces	ADEQUATE