

GLOBAL RISK SERVICES

WORKERS' COMPENSATION RISK ASSESSMENT REPORT

Account Name:	Apex Metalworks Inc.	Survey Date:	2026-02-18
Policy Number:	WC-93821-2026	Surveyor Name:	Marcus Vance, CSP
Insured Address:		Industry Segment:	

EXECUTIVE SUMMARY

Apex Metalworks displays an excellent corporate commitment to occupational safety and hazard mitigation across their custom sheet metal and tube fabrication plant. The physical shop floor is clean, well-organized, and utilizes modern, highly engineered safety controls. Employee safety training is documented and updated monthly. Most evaluated operational hazard categories are either Well-Controlled or Adequate. Only minor compliance recommendations are noted in laser sleeve utilization during manual packaging.

DETAILED FIELD OBSERVATIONS & RISK EVALUATION

1. Lifting (Industrial Ergonomics) — WELL-CONTROLLED

Hazard Context: Industrial ergonomics and lifting hazards related to handling heavy sheet metal raw stocks and dies.

Field Observations: Apex has completely engineered out manual overhead lifting of raw steel sheets. The shop has installed dual-arm vacuum lifters and overhead cranes on gantry rails above all major stamping stations. Workers are strictly forbidden from manual lifting of components exceeding 35 pounds.

Risk Control Recommendation: Continue to conduct routine inspection of the vacuum suction pads and hose lines to ensure vacuum lift integrity.

2. Lacerations / Cut Safety — ADEQUATE

Hazard Context: Control of puncture and cut injuries stemming from raw sheet metal handling and grinding operations.

Field Observations: Strict cut-resistant personal protective equipment (PPE) guidelines are established on the floor. Level A5 cut-resistant gloves and Kevlar sleeves are required in the sheet shear and assembly stations. However, the surveyor noted a minor gap where two packers in the shipping bay were wearing only low-grade leather work gloves while handling finished metal trims with sharp corners.

Risk Control Recommendation: Extend the mandatory Level A5 glove and sleeve policy to all final packaging and loading dock areas where raw metal edges are exposed.

3. Material Loading / Unloading & Securement — WELL-CONTROLLED

Hazard Context: Forklift and heavy machinery operations involving loading flatbeds and storage yard logistics.

Field Observations: Material handling lanes are clearly defined and painted safety yellow. Forklifts are equipped with flashing proximity sensors. Finished goods destined for shipping are bound with automated hydraulic strapping machines in a dedicated safety cage, removing workers from manual strapping risks.

Risk Control Recommendation: No critical corrective actions needed. Maintain current load-securement training standards.

4. Overhead Lifting Equipment — ADEQUATE

Hazard Context: Use and structural integrity of overhead cranes, hoists, rigging slings, and crane hooks.

Field Observations: The shop utilizes four overhead bridge cranes. Annual third-party inspection certifications are current (last conducted Nov 2025). Operators run daily pre-use inspection checklists, which were verified on-site. The rigging sling lockers were locked and organized, containing well-labeled nylon and wire ropes.

Risk Control Recommendation: Ensure that the unique load capacity markings painted on crane bridges remain highly visible and are not obscured by dust or grease accumulation. CNA RISK CONTROL SERVICES
WORKERS' COMPENSATION FIELD REPORT

5. Machine Guarding & Electrical Safety — WELL-CONTROLLED

Hazard Context: Physical point-of-operation machinery guards and electrical Lockout/Tagout procedures.

Field Observations: All hydraulic press brakes and CNC punch presses are equipped with dual-palm triggers and active light curtains. Interlocks were functionally tested by the surveyor and found to instantly halt operations when breached. Lockout/Tagout stations are heavily stocked, and machines have specific, laminated, photo-illustrated LOTO procedures attached directly to the chassis.

Risk Control Recommendation: Maintain the current zero-tolerance policy for bypassed guards. No corrective recommendations.

6. Occupational Disease & Illness — ADEQUATE

Hazard Context: Control of employee exposure to noise, toxic fumes from welding, and hexavalent chromium.

Field Observations: The welding department is equipped with localized trunk-source extraction vents that discharge fumes to external exhaust filtration units. Personal air-monitoring records from 2025 indicate hexavalent chromium exposure levels are well below OSHA permissible exposure limits (PEL). Heavy grinding stations require custom molded ear plugs.

Risk Control Recommendation: Ensure localized dust exhaust hood filters are cleaned weekly as part of the facility's preventative maintenance plan.

7. Walking / Working Surfaces — WELL-CONTROLLED

Hazard Context: Housekeeping, fluid leaks, slip-and-fall hazards, and floor maintenance.

Field Observations: Excellent general housekeeping was observed on all main walkways. Dry floor policies are supported by secondary drip trays beneath all stamping machine hydraulic manifolds. Spills of lubricants are cleaned instantly using absorbents stored in readily visible safety barrels.

Risk Control Recommendation: Ensure that safety barrels are refilled with absorbent granules on a weekly basis.

8. Elevated Work Surfaces — NOT APPLICABLE

Hazard Context: Stairs, platforms, fall arrest harnesses, and elevated mezzanine structures.

Field Observations: This facility is entirely single-story. No maintenance tasks or storage tasks are performed above ground level. Roof access is restricted to licensed HVAC subcontractors who operate under standard fall restraint policies.

Risk Control Recommendation: None. Category is considered out of scope due to single-story operations.
