

NON-CONFORMANCE REPORT (NCR) & CAPA RECORD

AS9100D §8.7 Control of Nonconforming Outputs | IPC-A-610 Class 3 / J-STD-001

NCR #: NCR-2026-049 | Status: OPEN | Archived: 2026-10-02 11:42:09

1. HARDWARE IDENTIFICATION & DISCREPANCY PROFILE

NCR Number:	NCR-2026-049	Severity Class:	Critical (Class 3)
Assembly Part #:	PCIe-SpaceWire-Monitor (Rev D)	Current Status:	Open
Board Serial (S/N):	01057897	Containment Date:	2026-10-02
Standard Clause:	AS9100D §8.7 / IPC-A-610 Class 3	Assigned Owner:	Manufacturing Engineering

2. DEFECT DESCRIPTION & OBJECTIVE NON-CONFORMANCE EVIDENCE

WIN10 app in manufacturing does not have an ATP loop...Alex could not get the Linux to work with his limited time. I brought the board to my office where apparently Pete gave me a different userapp (WIN10) dated the same date as the one in manufacturing but it has 38 tests not 31. ATP loop exists but keep getting WDF BSOD during ATP.

3. ROOT CAUSE ANALYSIS [METHODOLOGY: UNDER INVESTIGATION]

Root cause investigation under AS9100D §8.7 and IPC-A-610 Class 3.

4. IMMEDIATE CONTAINMENT & CORRECTIVE / PREVENTATIVE ACTIONS (CAPA)

continue to test the ATP loop to see if my motherboard is the issue or if there is something wrong with software., loses LOCK LED after being on for a while. 100 MHz differential coming out of the PCIe CLK generator still there tho. 3 different userapps! different drivers!, no version control.

5. AUDIT TRAIL, RECORD REVISIONS & MODIFICATION TIMESTAMPS

Date & Time (UTC/Local)	Author / Role	Change Details & Lifecycle Status
2026-10-02 11:42:09	Manufacturing Engine	NCR details updated and verified.
2026-10-02 10:53:35	Manufacturing Engine	Initial Non-Conformance Report logged and containment baseline

6. QUALITY ENGINEERING VERIFICATION & CONCURRENCE

Reviewed & Verified By: Manufacturing Engineering

Sign-off Timestamp: 2026-10-02 11:42:09

QMS Authorization: AS9100D §8.7 / IPC-A-610 Certified Delegated Quality Authority

Disposition Decision: Disposition verified & closed in compliance matrix.