Source Data From: eSolderControl		eSolderControl	v3.PriPcb		
		eSolderControl			
Variant: None		-			
variant.		None		_	
Creation Date:	21.01.2018	11:27:06			
Print Date:	21-Jan-18	11:27:18 AM			
			-		
Footprint	Comment	#Column Name E	Designator	#Column Name Error:Description	Quantity
HPS13C	HPS13C	"Goldmir Hame L	BQ1	"Columnative Error Secondarion	1
C0603	0.01u	[C1, C3, C4, C6	┥	4
C0603	0.1u	1	C2, C5, C10, C11, C12, C13, C14, C15,	┥	13
23003	J. 14	[C17, C18, C19, C22, C23		13
C0603	10u		C7, C8, C20, C21	┥	4
C0603	4.7u		C9	=	1
C0603	1u		C16	=	1
C0603	2.2u		C24, C25	=	2
C0603	6p		C26, C27	=	2
LQFP100	STM32F407V		DD1	╡	1
	MAX31856MUD		DD2, DD3	-	2
40X120-14N			,		
SOT95P245X	24AA08		DD4	7	1
145-5N					
R0603	200		R1, R8	7	2
R0603	0		R2, R3, R4, R5, R6, R7	7	6
TS_6x6			SB1, SB2, SB3	7	3
LED			VD1	7	1
0603_Green					
LED			VD2		1
0603_RED					
DS1066-02M	DS1066-02M	1	X1, X2, X7, X11, X12		5
PBS2-12	PBS2-12	1	X3, X8		2
DS1066-05M	DS1066-05M		X4, X5		2
PLS2-3	PLS2-3		X6		1
DS1066-05M	DS1066-06M		X9		1
	PLS-4		X10		1
PLS-4			ZQ1		1
	24MHz				58