...2-course-projects\Project-6-hourmeter\PLC2 Project 6 Hourmeter.ACD

Total number of rungs in routine: 7

Is the plant running? System_Running StartCounting Seconds StartCounting -TON-Timer On Delay (EN)Timer SecondsTimer Preset 1000 (DN) Accum SecondsTimer.DN -ADD Add Source A Hourmeter_Seconds 0 Source B Hourmeter_Seconds Dest SecondsTimer (RES) Minutes This would have been a lot easier had I used counters GEQ-MOV Grtr Than or Eql (A>=B) 3 Move Source A Hourmeter_Seconds Source 0 0 60 Source B Dest Hourmeter_Seconds -ADD-Add Source A Hourmeter_Minutes 0 Source B Dest Hourmeter_Minutes Hundreds of hours -GEQ--MOV Grtr Than or Eql (A>=B) Move Source A Hourmeter_Minutes 0 Source 60 Dest Hourmeter_Minutes Source B -ADD-Source A Hourmeter_HundredsHours 0 Source B 1 Hourmeter_HundredsHours Dest

Total number of rungs in routine: 7

...2-course-projects\Project-6-hourmeter\PLC2 Project 6 Hourmeter.ACD

