Making CAD education accessible to anyone, anywhere.

Autodesk Fusion Hotkey Sheet

Mac & Windows • 2024 Edition

Table of Contents

Design Workspace

Command	Windows OS	Mac OS
Appearance	A	A
As-built Joint	Shift + J	Shift + J
Compute All	CTRL + B	CMD + B
Delete	Del	Del
Extrude	E	E
Freeform Selection	2	2
Hole	H	H
Joint	J	J
Measure	I	I
Model Fillet	F	F
Design Shortcuts	S	S
Move	M	M
Paint Selection	3	3
Press Pull	Q	Q
Scripts and Add-ins	Shift + S	Shift + S
Toggle Component Color Cycling	Shift + N	Shift + N
Toggle Visibility	V	V
Window Selection	1	1

PhotoDesignOnline.com

Sketch Environment

Command	Windows OS	Mac OS
2-point Rectangle	R	R
Center Diameter Circle	C	C
Line	L	L
Sketch Shortcuts	S	S
Normal / Construction	X	X
Offset	O	O
Project	P	P
Sketch Dimension	D	D
Trim	T	T

v2.0

Canvas Selection

Command	Windows OS	Mac OS
Copy	CTRL + C	CMD + C
Cut	CTRL + X	CMD + X
Orbit	Shift + Hold Middle Mouse	Shift + Hold Middle Mouse
Orbit around point	Shift + Click then Hold Middle Mouse	Shift + Click then Hold Middle Mouse
Pan	Hold Middle Mouse	Hold Middle Mouse
Paste	CTRL + V	CMD + V
Redo	CTRL + Y	CMD + Y
Undo	CTRL + Z	CMD + Z
Zoom	Roll Middle Mouse	Roll Middle Mouse

v2.0

Form Environment (T-Splines)

Command	Windows OS	Mac OS
Grow selection	Shift + Up Arrow	Shift + Up Arrow
Invert selection	Alt + N	CMD + N
Loop grow selection	Alt + O	CMD + O
Loop selection	Alt + P	CTRL + P
Next U	Alt + Right Arrow	CTRL + CMD + Right Arrow
Next V	Alt + Up Arrow	CTRL + CMD + Up Arrow
Previous U	Alt + Left Arrow	CTRL + CMD + Left Arrow
Previous V	Alt + Down Arrow	CTRL + CMD + Down Arrow
Range selection	Alt + M	CMD + M
Ring grow selection	Alt + K	CTRL + K
Ring selection	Alt + L	CTRL + L
Ring shrink selection	Alt + J	CTRL + J
Select edge ring	Double-click an edge	Double-click an edge
Select face ring	Select two faces then double-click a third face	Select two faces then double-click a third face
Shrink selection	Shift + Down Arrow	Shift + Down Arrow
Toggle box mode	Alt + 1	CTRL + 1
Toggle control frame mode	Alt + 2	CTRL + 2

Form Environment (Continued)

Command	Windows OS	Mac OS
Toggle smooth mode	Alt + 3	CTRL + 3
Add geometry	Alt + Drag	Option + Drag
Add geometry and keep creases	Alt + Control + Drag	Option + Command + Drag

v2.0

Generative Design Workspace

Command	Windows OS	Mac OS
New Generative Study	N	N
Study Settings	E	E
Structural Constraints	C	C
Structural Loads	L	L

Render Workspace

Command	Windows OS	Mac OS
Appearance	A	A

Animation Workspace

Command	Windows OS	Mac OS
Auto Explode All Levels	U	U
Manual Explode	E	E
Publish Video	P	P
Transform Components	M	M
View	C	C

ProductDesignOnline.com

v2.0

Simulation Workspace

Command	Windows OS	Mac OS
DOF View	CTRL + D	CMD + D
Force	F	F
Groups View	CTRL + G	CMD + G
Model View	CTRL + L	CMD + L
New Simulation Study	N	N
Results View	CTRL + R	CMD + R
Settings	E	E
Structural Constraint	C	C
Structural Loads	L	L

Manufacture Workspace

Command	Windows OS	Mac OS
Duplicate	CTRL + D	CMD + D
Generate Toolpath	CTRL + G	CMD + G
Scripts and Add-Ins	Shift + S	Shift + S
Show Log	CTRL + L	CMD + L

v2.0

Drawing Workspace

Command	Windows OS	Mac OS
Balloon	B	B
Center Mark	C	C
Delete	Delete	Delete
Dimension	D	D
Move	M	M
Projected View	P	P
Text	T	T

v2.0

Electronics Workspace

Command	Windows OS	Mac OS
Activate command line	/	/
Add Hold	H	H
Add Part	P	P
Add Text	T	T
Bus	B	B
Change	C	C
Copy	CTRL + C	CMD + C
Delete	Delete (Backspace)	Delete (Backspace)
Dimension	D	D
DRC	CTRL + D	CMD + D
ERC	CTRL + E	CMD + E
Errors	E	E
Grid	G	G
Label	Shift + L	Shift + L
Manual Route	R	R
Move	R	R
Name	N	N
Net	R	R
New Device	Alt + CTRL + 3	Option + CMD + 3

v2.0

Electronics Workspace (continued)

Command	Windows OS	Mac OS
New Footprint	Alt + CTRL + 2	Option + CMD + 2
New Symbol	Alt + CTRL + 1	Option + CMD + 1
Package 3D Create	Alt + CTRL + 4	Option + CMD + 4
Pad	O	O
Pad Array	Shift + O	Shift + O
Pin	P	P
Pin Array	Shift + P	Shift + P
Redo	CTRL + Y	CMD + Shift + Z
Ripup	U	U
Ripup All Polygons	Alt + Shift + P	Option + Shift + P
Route Diff Pair	CTRL + R	CMD + R
Route Multi	Shift + R	Shift + R
Run Script	Alt + Shift + S	Option + Shift + S
Run ULP	Shift + U	Shift + U
SMD	P	P
SMD Array	Shift + P	Shift + P
Stop	ESC	ESC
Undo	CTRL + Z	CMD + Z
Value	V	V

v2.0

Electronics Workspace (continued)

Command	Windows OS	Mac OS
Via	Alt + V	Option + V
Zoom to Fit	F6	F6
Switch Sch Doc	CTRL + 1	CMD + 1
Switch PCB Doc	CTRL + 2	CMD + 2
PCB 3D View	CTRL + 3	CMD + 3
Shortcut Dialog	S	S

v2.0

System (saving)

Command	Windows OS	Mac OS
Recovery Save	CTRL + Shift + S	CMD + Shift + S
Save Version	CTRL + S	CMD + S

Ready to Master Fusion?

Join the **PDO Academy** today and gain instant access to our members-only courses and benefits:

- Our popular Fusion Masterclass (9 courses in 1)

- 8+ Fusion courses & tons of individual lessons

- Priority instructor support when you get stuck

- Members-only help forum with each lesson

- Members-only community for your personal projects

- Downloadable handouts & resources

- Course quizzes to test your new knowledge

- Exclusive software and service discounts**

Use code PDO30 to take $30 off our lifetime membership*