Appendix B - Internal Moisture Intrusion Checklist

Clear

Grey Black

Perform as soon as possible after moisture intrusion problems are reported.

1 Citorin as soon as possible after moistare intrasion problems are reported.					
Property Name: BONITA HILLS	Unit# 1404B				
Date Reported: 10/18/22	Inspector's Name: Dmitry Didenko				
Time Reported: 4:59 pm					

Type of moisture intrusion (clear, grey, black water):

Check Only One

Inspector's Initials	Comments/Follow-up
D.D.	
D.D.	
D.D.	

Inspection Item:

 ${\bf Staining/discoloration\ observed\ on\ building\ materials:}$

Yes No Inspector's Initials	Comments/Follow-up
-----------------------------	--------------------

 $Staining/discoloration\ observed\ near\ utilities:$

Yes	No		Inspector's Initials	Comments/Follow-up
-----	----	--	----------------------	--------------------

Building material impacted by moisture intrusion:

Location - which room / room(s) etc. Square Footages Wood moisture meter results Concrete moisture meter results

Hallways	AC Cabinet	Guest Bedroom	
dfv	dfv	df	
fv	dfv	df	
dfb	dfb	df	