Appendix B - Internal Moisture Intrusion Checklist

Perform as soon as possible after moisture intrusion problems are reported.

1 CHOIM as 300h as possible after moistare intrasion problems are reported.			
Property Name: SOMMERSET	Unit# 83		
Date Reported: 11/03/21	Inspector's Name: Mark Gordillo		
Time Reported: 12:00 am			

Type of moisture intrusion (clear, grey, black water):

Check Only One

		Inspector's Initials	Comments/Follow-up
Clear		M.G.	
Grey		M.G.	
Black	•	M.G.	

Inspection Item:

Staining/discoloration observed on building materials:

Ceiling

Floor/tack strips

Yes	No	Inspector's Initials	Comments/Follow-up
	✓	M.G.	
1		M.G.	

Staining/discoloration observed near utilities:

Yes No Inspector's Initials	Comments/Follow-up
-----------------------------	--------------------

Building material impacted by moisture intrusion:

Location - which room / room(s) etc.

Square Footages

Wood moisture meter results

Concrete moisture meter results

G/BATHROOM