## Appendix B - Internal Moisture Intrusion Checklist

Clear

Grey Black

Perform as soon as possible after moisture intrusion problems are reported.

1 Citorin as soon as possible after moistare intrasion problems are reported.		
Property Name: WOODBRIDGE	Unit# <b>112</b>	
Date Reported: 10/17/22	Inspector's Name: <b>Dmitry Didenko</b>	
Time Reported: 1:01 pm		

## Type of moisture intrusion (clear, grey, black water):

Check Only One

Inspector's Initials	Comments/Follow-up
D.D.	
D.D.	
D.D.	

## **Inspection Item:**

 ${\bf Staining/discoloration\ observed\ on\ building\ materials:}$ 

Yes	No	Inspector's Initials	Comments/Follow-up
-----	----	----------------------	--------------------

 $Staining/discoloration\ observed\ near\ utilities:$ 

	Yes	No		Inspector's Initials	Comments/Follow-up	1
--	-----	----	--	----------------------	--------------------	---

## Building material impacted by moisture intrusion:

Location - which room / room(s) etc. Square Footages Wood moisture meter results Concrete moisture meter results

Hallways	AC Cabinet	Guest Bedroom
fevv	efv	efv
efv	efv	efv
efv	efv	efv