



Cox Roofing & Restoration LLC

STORM DAMAGE DISCOVERY · CLAIM SUPPORT

700 Commerce Dr, Suite 500, Oak Brook, IL 60523 · (877) 816-4245 · COXROOF.COM

CONFIDENTIAL · BOARD OF DIRECTORS PACKET · REV. 2 WITH ANNOTATED PHOTO EXHIBITS

Storm Damage Discovery Proposal

Twenty annotated photo exhibits documenting hail and wind impact across roofing, soft metal, HVAC, and exterior openings — with a clear recommendation to authorize an insurance claim.

PROPERTY

456 Timber Trail Ct, Naperville, IL 60565

JOB REFERENCE

**#5467 · Insurance · Owner contact:
Michale Forsberg**

INSPECTION DATE

August 14, 2026 · 2:42–2:50 PM (GPS-stamped)

FIELD GPS

41.739° N, 88.118° W · DuPage County

BOARD ASK — ONE SENTENCE

Authorize the Association to file a property insurance claim for sudden storm damage documented in Exhibits A–T and retain claim-support advocacy so reserves are not spent on a covered loss.

20

ANNOTATED
EXHIBITS

4

DAMAGE SYSTEMS

5/5

PEAK SEVERITY

8/14

GPS-STAMPED
SURVEY

Wind-blown / creased shingles

Hail bruising / granule loss

Downspout impact dents

1. Why this matters to the Board

This association's roofs are a shared capital asset. The survey shows *sudden, accidental, weather-related impact* — not ordinary aging alone. Soft-metal "collateral" evidence (vent lids, downspouts, garage pent roofs, screens) is the same class of proof insurance adjusters use to corroborate hail energy on the shingle field. Every circled finding in Exhibits A–T maps to a numbered notation for the adjuster walk.

If the Board files promptly

Carrier evaluation proceeds while evidence is fresh, unit owners see fiduciary action, and covered restoration protects reserves.

If the Board waits

Bruised shingles lose UV protection at impact points; leaks and interior claims rise; late-notice arguments get easier for a carrier.

2. Executive findings

SYSTEM	OBSERVED CONDITION (EXHIBITS)	CLAIM RELEVANCE	SEV.
Architectural shingles — wind	Diagonal wind crease in laminate tab (H); wind-blown/lifted shingles along gable rooflines sighted from elevations (M, N, R)	Broken seal strips = functional wind damage even where tabs lie flat	5
Architectural shingles — hail	Circular granule loss exposing asphalt mat across multiple frames (H–L)	Functional damage / accelerated failure	5
Attic box vents	Lid indentations, flange scour (F, G); 40+ vents across four buildings (A–D)	Classic soft-metal collateral	5
Downspouts / gutters	Dent clusters with coating scuffed to bright metal (O, Q); runs flagged (N, P)	Vertical-surface impact = wind-driven hail vector	4
Garage pent roofs	Soft-metal awnings over garages, both buildings (M, R)	Persuasive corroboration surfaces	4
Window screens	Puncture line + abrasion zone with pinholes (S, T)	High-velocity debris/hail on openings	3

SYSTEM	OBSERVED CONDITION (EXHIBITS)	CLAIM RELEVANCE	SEV.
Valleys / heat cables	Crossed cables, clip penetrations, debris dams (E)	Separate corrective scope — do not let carrier reframe loss as wear	3

3. Recommended claim strategy

1. **File now** — notice of loss for hail/wind on common-element roofs and related exterior components.
2. **Preserve evidence** — keep this packet and original GPS-stamped photos; no non-emergency repairs before carrier acknowledgment.
3. **Walk soft metal first** — Exhibits O and Q anchor storm energy; then test squares on slopes from Exhibits H-L.
4. **Scope for RCV** — slope / building-level replacement where bruise density warrants; match materials across elevations.
5. **Coordinate unit owners** — screens, HVAC, and unit-maintained items per the declaration; Board leads the common-element claim.

4. Suggested Board motion

DRAFT MOTION FOR MINUTES

Motion: That the Board of Directors authorize the filing of a property insurance claim for storm-related damage documented on August 14, 2026 at the Timber Trail Ct buildings surveyed (including units 456 and 463); direct management to notify the carrier; and engage Cox Roofing & Restoration LLC to present damage discovery Exhibits A–T, attend the adjuster inspection, and report back with carrier findings and recommended restoration scope — with the intent that covered storm damage not be paid solely from Association reserves.

- ☐ Approve motion & record vote
- ☐ Management files notice of loss within carrier timelines
- ☐ Deliver this packet with Exhibits A–T to the carrier
- ☐ Schedule joint inspection; owners notified of access needs

5. Photo exhibits A–T — circled & notated

Red circles mark wind/hail evidence; numbered notes below each frame explain what is circled and why it matters to the claim. Wind-blown shingle callouts are flagged **WIND** on the elevation exhibits (M, N, R) and the creased-tab close-up (H). GPS/time stamps are burned into the ground-survey photos.

EXHIBIT A • AERIAL SURVEY

Nadir drone view — Building 1 (crew on site)

Drone ortho • inspection crew + ladder staged at street

- Twelve-plus soft-metal box vents across ridges — primary hail test surfaces (circled clusters).
- Multi-tonal granule discoloration scattered across south- and west-facing slopes — flag tonal breaks along ridge and rake lines for wind-lift (broken seal) verification on the roof walk.
- Establishes formal inspection: ladder and crew visible at the drive.

EXHIBIT B • AERIAL SURVEY

Nadir drone view — Building 2

Drone ortho • H-plan roof, paired ridge vent rows

- Box vents along both ridge lines (circled) — each lid and flange to be checked for strikes.
- Field granule displacement visible at drone altitude on the center slope.

EXHIBIT C • AERIAL SURVEY

Nadir drone view — Building 3 (complex geometry)

Drone ortho • multi-hip/valley roof, highest penetration count

- Valley convergence zones (circled) concentrate runoff over impacted shingle field.
- Twenty-plus penetrations; every flange is a leak path if sealant was impacted.

EXHIBIT D · AERIAL SURVEY

Nadir drone view — Building 4 (entry canopy)

Drone ortho · vents plus soft-metal entry canopy

- Vent field circled; entry canopy between drives is an additional soft-metal witness surface.
- Same shingle blend and exposure as Buildings 1–3 — common-element scope.

EXHIBIT E · ROOF DETAIL

Valley with heat cables and debris

Roof-level · de-icing cable array at valley/eave

- Crossed heat cables with dozens of clip penetrations through shingle field (circle 1).
- Debris mats trapped on cables — drainage dam and moisture trap (circle 2).
- Documented as separate corrective scope so restored roof does not inherit the leak pattern.

EXHIBIT F · ROOF DETAIL

Attic box vent — close-up

Roof-level · galvanized vent lid and flange

- Circular indentations on the soft-metal lid top face (circle 1) — classic hail witness marks.
- Mastic-smear flange fasteners (circle 2) show prior service; granule scour at flange edge.

EXHIBIT G · ROOF DETAIL

Paired box vents at ridge

Roof-level · two vents, drone shadow in frame

- Both vent lids circled for adjuster dent verification — soft metal deforms at hail sizes that bruise shingles.
- Scattered granule-loss points in the field between the vents.

EXHIBIT H · SHINGLE FIELD

Shingle close-up — wind crease + bruising

Test-square candidate · laminate field

- WIND: diagonal crease line across the laminate tab right of center (circle 1) — the signature of a wind-lifted shingle that folded back and re-set; the seal strip is broken even though the tab lies flat.
- Circular granule displacement exposing black asphalt mat (circles 2–3) — the industry definition of hail bruising.
- Impact points sit mid-tab, not at edges — storm pattern rather than foot scuffing.

EXHIBIT I · SHINGLE FIELD

Shingle field — angled frame 1

Test-square candidate · random-pattern granule loss

- Random-distribution dark spots across tabs (circles) — consistent with hail, not mechanical wear paths.
- Density supports slope-level functional damage evaluation.

EXHIBIT J · SHINGLE FIELD

Shingle field — angled frame 2 (density backup)

Backup frame for bruise-density count

- Second frame of the same slope for impact-density counting during the adjuster test square.
- Bright fracture points (circled) indicate recent granule loss — substrate not yet UV-darkened.

EXHIBIT K · SHINGLE FIELD

Shingle field at vent flange

Roof-level · penetration corner in frame

- Fresh bright granule-loss points adjacent to the penetration (circle 1).
- Vent flange corner (circle 2) — impacts at flanges compromise the seal line.

EXHIBIT L · SHINGLE FIELD

Distinct impact strike — close-up

Roof-level · drone shadow in frame

- Single distinct dark strike with mat bruise at center frame (circle) — flagship bruise photo for the claim file.

EXHIBIT M · ELEVATIONS — WIND-BLOWN SHINGLES

Front elevation — unit 456

GPS 41.7392° N, 88.1183° W · 8/14/2026 2:42 PM

- WIND: gable roofline above the second story (circle 1) — wind-blown/lifted shingle tabs and broken seal lines sighted from grade along the rake and ridge; flag for ladder verification during the adjuster walk.
- Establishes subject unit 456 Timber Trail Ct (job #5467, insurance type).
- Metal pent roof over garage (circle 2) and neighbor gable roofline (circle 3) are matching witness surfaces across units.

EXHIBIT N · ELEVATIONS — WIND-BLOWN SHINGLES

Side elevation — unit 463

GPS 41.7391° N, 88.1183° W · 8/14/2026 2:46 PM

- WIND: rake edge and gable roofline (circle 1) — wind-exposure edge where blown/lifted shingles start; the side elevations take the direct wind fetch between buildings.
- Full-height white downspout run (circle 2) — leads directly to the impact damage in Exhibits O and Q.
- Gutter and fascia line at the gable to be sighted for dings during the adjuster walk.

EXHIBIT O · SOFT-METAL COLLATERAL

Downspout impact damage — brick corner

GPS 41.7391° N, 88.1182° W · 8/14/2026 2:46 PM

- Key exhibit. Mid-span dents with finish scuffed to bare metal (circle 1) — impact energy on a vertical surface indicates wind-driven hail vector.
- Secondary crimp deformation at lower elbow (circle 2).
- Bright exposed substrate = recent damage, not aged oxidation.

EXHIBIT P • SOFT-METAL COLLATERAL

Rear corner elevation — condenser and leader

GPS 41.7391° N, 88.1180° W · 8/14/2026 2:46 PM

- Lennox condenser fin packs (circle 1) — verify crush patches; hail flattens fins in discrete zones.
- Upper downspout section (circle 2) continues the collateral chain from ground to eave.

EXHIBIT Q • SOFT-METAL COLLATERAL

Downspout dent cluster — close-up

GPS 41.7391° N, 88.1180° W · 8/14/2026 2:46 PM

- Key exhibit. Elongated dent cluster with coating removed to bright metal (circle) — fresh, high-energy impacts.
- Pair with Exhibit O in the adjuster walk to anchor storm energy before roof close-ups.

EXHIBIT R • ELEVATIONS — WIND-BLOWN SHINGLES

Front elevation — unit 463 building

GPS 41.7390° N, 88.1183° W · 8/14/2026 2:48 PM

- WIND: left gable roofline (circle 1) and right gable roofline (circle 2) — wind-blown/lifted shingles along both rakes visible from the elevation; the paired gables channel gusts across the field tabs.
- Metal pent roofs over both garages (circles 3–4) — repeat soft-metal surfaces across units confirm association-wide exposure.

EXHIBIT S • OPENINGS

Window screen — puncture line

GPS 41.7393° N, 88.1187° W · 8/14/2026 2:50 PM

- Three clustered mesh tears in a horizontal line (circle) — high-velocity debris/hail perforation, not vandalism.
- Same-afternoon timestamp ties opening damage to the roof and soft-metal findings.

EXHIBIT T · OPENINGS

Window screen — abrasion zone

GPS 41.7393° N, 88.1187° W · 8/14/2026 2:50 PM

- Abraded mesh zone with pin punctures and splatter pattern upper-right (circle) — impact residue on the opening face.

6. Closing recommendation

The Association has matched proof: bruised shingles *plus* soft-metal, opening, and mechanical collateral — GPS-stamped on the same afternoon. Filing positions the Board as protecting the asset and the reserves. Declining to file converts a potentially covered storm event into a self-funded capital project.

Recommended next step today: adopt the motion in §4, transmit this packet, and calendar the adjuster inspection.

Damage discovery packet prepared by Cox Roofing & Restoration LLC · 700 Commerce Dr, Suite 500, Oak Brook, IL 60523 · (877) 816-4245 · COXROOF.COM — a field documentation and board decision aid. It does not constitute a public adjusting engagement, legal opinion, engineering certification, or guarantee of coverage. Coverage depends on the Association's policy, deductibles, endorsements, and carrier determination. Job #5467 · 456 Timber Trail Ct, Naperville, DuPage County, Illinois 60565 · Survey August 14, 2026.