
Changelog

SGPA3
Automated Process Management System



Changelog Version 2026/286

Period: 09/01/2026 to 09/21/2026

Revision 00

Date: 10/13/2026

Some applications mentioned in this report may not be available in the package of functionalities installed in your SGPA 3.0

+55 (18) 3622-2270
Av. Brasília, 2.121 - Edif. New York Tower
Jardim Nova York - Araçatuba/SP



Thank you for being a SGPA 3.0 user!

We update our system frequently to fix bugs, improve performance, and add new features to enable a better user experience and contribute to management with higher quality and efficiency.

+55 (18) 3622-2270
Av. Brasília, 2.121 - Edif. New York Tower
Jardim Nova York - Araçatuba/SP

1. SGPA3 4
1.1 Improvements 4
1.1.1 Monit+ Operating Conditions by Lane 4
1.1.2 Online Command – Maximum Speed 8
1.1.3 Module – CDA Panel 11
1.1.4 PBI Report – Dynamic Report 11
2.1 Bugs 13
2.1.1 Monitoring – Slowness 13
2.1.2 Maps – Water Resources Management (GRH) 13
2.1.3 Maps – Unit/Equipment Exchange 13
2.1.4 PBI Report – Online Command and Historical Alarms 14
2.1.5 PBI Reports – Application of Fertigation 14
2.1.6 Analytical Map – Fertigation 15
2.1.7 Records – Station / Rain Gauge Type 15
2.1.8 Maps/Monitoring – Meteorology 15
2.1.9 Records – Alerts 16

1. SGPA3

1.1 Improvements

1.1.1 Monit+ Operating Conditions by Lane

Improvements made to the Monit+ module, on the Operating Conditions/Equipment Management screen, to improve the configuration of rules and equipment monitoring.

New Condition by Lane ("Is Out"): Implemented a new operator to replace the need for multiple manual rules. Now, the system allows you to set minimum and maximum limits such as pressure or speed. The visual indicator remains green as long as the value is within the acceptable range and signals in red if the equipment operates outside the established limits.




Figure 1 – New "Is Out" condition




Figure 2 – "Is out" condition

+55 (18) 3622-2270
Av. Brasília, 2.121 - Edif. New York Tower
Jardim Nova York - Araçatuba/SP




Figure 3 – Edit Conditions - Operations Conditions screen




Figure 4 – Sugarcane Truck Conditions

Standardization of Binary Fields: The Engine On and Load Status parameters, which previously used free numeric values (0 or 1), have been converted to selections in user-friendly text format (On/Off and Loading/Not Loading), making it easier to configure and view in the subtitles.

+55 (18) 3622-2270
Av. Brasília, 2.121 - Edif. New York Tower
Jardim Nova York - Araçatuba/SP

To validate, access the system, log in to Monit+, click on the icon to open the Edit Operating Conditions modal on a type of equipment. Add or adjust conditions using the new lane operators and select the text-based binary fields to confirm visual behavior and signaling




Figure 5 – Operating Conditions – Harvesting Conditions

+55 (18) 3622-2270
Av. Brasília, 2.121 - Edif. New York Tower
Jardim Nova York - Araçatuba/SP




Figure 6 – Conditions of Operations – Harvester Loading Status




Figure 7 – Operating Conditions – Harvester Engine On

Accessed in: Upper Menu > Monit+ > Equipment Management > Edit Operations Conditions > Conditions

+55 (18) 3622-2270
Av. Brasília, 2.121 - Edif. New York Tower
Jardim Nova York - Araçatuba/SP

1.1.2 Online Command – Maximum Speed

Improvements made to optimize the sending of online commands and the display of speed information on harvester (1) and transfer (2) type equipment. The field referring to the online command "Maximum alarm speed, 3 digits" has been adjusted to accept decimal values with up to one place after the decimal point (allowing for more precise parameterization, such as 111.1), aligning with the existing behavior for harvesters.

Additionally, the On-Board Configuration screen has been improved to ensure that the labels and the maximum effective speed fields correctly display the decimal places sent by the system. To validate, access the suggested paths and select a Harvester or Transfer type equipment, choose the option "Maximum alarm speed, 3 digits" and confirm that the system accepts and saves values with decimals, or check the data display on the On-Board Configuration screen.




Figure 8 – Online monitoring command

+55 (18) 3622-2270
Av. Brasília, 2.121 - Edif. New York Tower
Jardim Nova York - Araçatuba/SP




Figure 9 – Online command monitoring – Success message "Online command created successfully"




Figure 10 – Monit+ online command




Figure 11 – Monit+ online command - Success Message "Online command sent successfully"

+55 (18) 3622-2270
Av. Brasília, 2.121 - Edif. New York Tower
Jardim Nova York - Araçatuba/SP




Figure 12 – Online Command - Top Menu




Figure 13 – Online Command - Top Menu Success Message "Online Command Created Successfully"

Accessed at:

1 - Upper Menu > Online Control > New Online Control > Equipment 1 (Harvester) and 2 (Transfer) > Select equipment from the list > Option to be chosen -> Maximum alarm speed, 3 digits.

2 - Side Menu > Modules > Online Command > New Online Command > Equipment 1 (Harvester) and 2 (Transfer) > Select equipment from the list > Option to be chosen -> Maximum alarm speed, 3 digits.

3 - Top Menu > Monitoring> Pop-up of the selected Equipment Harvester or Transfer > Online Command > Maximum Speed Alarm 3 Digits

4 - Top Menu > Monit+ > Pop-up of the selected equipment Harvester or Transfer > Online Command >Maximum Speed Alarm 3 Digits

5 - Side Menu > Maintenance > On-Board Configuration > Choose equipment 1 or 2, select "Send to Ship" and update

+55 (18) 3622-2270
Av. Brasília, 2.121 - Edif. New York Tower
Jardim Nova York - Araçatuba/SP

1.1.3 Module – CDA Panel

Performance improvement performed in the CDA module, for all tabs such as "Cotton" and "PBI", to address excessive slowness and display failures when querying periods longer than one day. The query has been optimized to fetch only the minimum required range of data instead of a fixed period of six months, and the traceability function has been improved to avoid reading records in full, replacing the process with a direct filter. With these modifications, the screen loading and response time has been drastically reduced from more than 2 minutes to approximately 15 seconds. To validate, access the CDA module, select the desired tab, apply a filter with a period longer than one day, and confirm that the data is displayed quickly and without crashes.




Figure 14 – CDA Panel Tabs - Cotton

Access in: Top Menu > CDA Panel > All Tabs

Access in: Side Menu > Reports > PBI > Digital Certificate of Cotton

1.1.4 PBI Report – Dynamic Report

+55 (18) 3622-2270
Av. Brasília, 2.121 - Edif. New York Tower
Jardim Nova York - Araçatuba/SP

Improvement implemented in the PBI Dynamic Report to make the Journey Utilization metric (%) available for the Perennial Vertical. The new metric was integrated and made available as a selection option for analysis in both the Table and Graph tabs. To validate, access the system through the path PBI > Reports > Dynamic Report, select the desired report and confirm that the Journey Utilization option is available for filtering and visualization of the data.




Figure 15 – Dynamic Report – Table Tab




Figure 16 – Dynamic Report – Graph Tab

+55 (18) 3622-2270
Av. Brasília, 2.121 - Edif. New York Tower
Jardim Nova York - Araçatuba/SP

Access in: Side Menu > PBI > Reports > Dynamic Report

2.1 Bugs

2.1.1 Monitoring – Slowness

Adjustments made to the SGPA to optimize the initial loading time of the system and the Online Monitoring screen. Processing has been improved, eliminating the slowness when opening the environment and speeding up the visualization of large fleets. To validate, access the SGPA, log in and open Online Monitoring to check the speed of complete loading of the screen and assets.

Access in: Top Menu > Monitoring

2.1.2 Maps – Water Resources Management (GRH)

Adjustment made in the calculation of the Water Balance in the SGPA, where the data query was incorrectly adding the information of all registered water sectors, including those that were already inactive. With the correction applied, the system started to consider only the active sectors, normalizing the volumes of rain and eliminating distortions in the reports.

Access in: Top Menu > Maps > GRH > Water Balance

2.1.3 Maps – Unit/Equipment Exchange

Adjustment applied to resolve a failure that prevented the loading of equipment on the Maps screen when changing units using traditional user and password access. The system was applying an incorrect verification rule after the exchange, causing the dashboard to remain linked to the previous unit and not display the updated information. With the adjustment, the unit switching was corrected, ensuring

+55 (18) 3622-2270
Av. Brasília, 2.121 - Edif. New York Tower
Jardim Nova York - Araçatuba/SP

that the data, maps and equipment of the new unit are loaded normally. To validate, access the system with a traditional login, use the side menu to change units and confirm on the analytical map that the information and machinery of the new unit appear correctly.

Access in: Top Menu > Maps > Analytics > Equipment Details > Side Menu (Unit) > select another unit

2.1.4 PBI Report – Online Command and Historical Alarms

Adjustment applied to resolve failures and divergences in the calculation of the triggered time of historical alarms (such as the speed alarm) displayed in BI reports. The system had inconsistencies in the accumulated daily hours — displaying sums greater than 24 hours or times much higher than those verified in the actual tracks of the equipment. With the change, a new processing routine was implemented with greater detail of the monitoring data and optimized integration with the BI function. To validate, access the alarm report in the system, apply a daily filter or by fleet/unit, and confirm that the alarm duration time count faithfully corresponds to the history of machinery tracks.

Access in: Side Menu > Reports > PBI > Online Commands and Alarms > Alarms

2.1.5 PBI Reports – Application of Fertigation

Adjustment applied to the PBI Report of Fertigation Application to solve failures in the recording of the status table data for the Tractor and Hydroroll equipment, which resulted in the incorrect display of the value "-1 * NOT DEFINED *" (behaved as maximum value) in the farm/field field. With the correction in the way the recording is performed, the report now correctly displays the source information. In addition, an adjustment was made in the processing of the blade to correct temporary inconsistencies.

Access in: Side Menu > PBI > Reports > Fertigation Application Report

+55 (18) 3622-2270
Av. Brasília, 2.121 - Edif. New York Tower
Jardim Nova York - Araçatuba/SP

2.1.6 Analytical Map – Fertigation

Adjustment applied to the Analytical Map and PBI Reports of Fertigation Application to solve failures that prevented the display of application IDs (in Reel type equipment). The problem occurred due to limitations in search time and crashes in the prior processing of irrigations greater than 24 hours.

With the extension of the search period and the optimization of processing routines, the display of data has been normalized. To validate, access the analytical map or fertigation report and confirm that the information is displayed correctly.

Access in: Top Menu > Maps > Analytics

Access in: Side menu > PBI > Reports > Fertigation Application Report

2.1.7 Records – Station / Rain Gauge Type

Adjustment applied to the Station Type / Rain Gauge Records screen to solve a loading failure that prevented the listing of equipment (such as the test fleet). With the fix, the normal loading of information was reestablished.

Access in: Side Menu > Records > Equipment > Station Rain Gauge Type.

2.1.8 Maps/Monitoring – Meteorology

Adjustment applied to the processing of meteorological data to correct a failure that caused delays in updating rain information from rain gauges. The problem occurred due to an error in the processing routine, which generated crashes and delays in real-time monitoring. With the correction, the data flow was normalized, ensuring the agile and accurate display of precipitation information.

Access in: Top Menu > Maps > Meteorology > Weather Maps> Select the Period> Data > Rain Accumulation

+55 (18) 3622-2270
Av. Brasília, 2.121 - Edif. New York Tower
Jardim Nova York - Araçatuba/SP

Access in: Top Menu > Monitoring > Online Equipment > Rain Gauge

2.1.9 Records – Alerts

Adjustment applied to correct the display of data in the field of values and properties of operations for the type of equipment "53 - Vinasse Truck". The problem occurred due to the absence of correct cadastral links for this category of machinery, which caused the system to display incorrect or blank values (such as "undefined"). With the correction, all property links and descriptions of operations were duly updated, reestablishing the correct listing of information for the creation of alerts and reports. To validate, access the system, select a Vinasse Truck, in information type check Online Monitoring and confirm that the codes and values of operations appear normally in the corresponding fields.

Access in: Side Menu > Records > Alerts > Expression Condition > New

If you have any questions or other clarifications, please contact us via email suporte@solinftec.com.br or call +55 18 3622 2270.

+55 (18) 3622-2270
Av. Brasília, 2.121 - Edif. New York Tower
Jardim Nova York - Araçatuba/SP