## 5L40-E, 5L50-E

(800) 843-2600 • (802) 463-9722 • F: (802) 463-4059 • www.sonnax.com

©2011 Sonnax Industries, Inc.

(1) 55211-04K

**TCC Regulator Valve** & Sleeve Kit



Helps cure:

- TCC slip/ratio codes
- Transmission/Converter overheat

Note: Requires tool kit F-55211-TL4 & the VB-FIX reaming fixture.

(2) 55211-21



**TCC Control Valve** 


For single valve pumps

Helps cure:

- Incorrect TCC apply & release
- No lockup/falling out of lockup hot

Note: Requires tool kit F-55211-TL22, & the **VB-FIX** reaming fixture

(3) 55211-22K



For dual valve pumps

**Dual Valve** 

Fluid Pump

Assembly

4

Helps cure:

- Incorrect TCC apply & release
- No lockup/falling out of lockup hot

Note: Requires tool kit F-55211-TL22, & the VB-FIX reaming fixture.

55211-08K



Helps cure:

2

- Low line pressure
- Worn PR valve bore

Note: Requires tool kit 55211-TL8.



5 55209-01K

Valve spool diameters .531" & .492"

**Boost Valve.** Sleeve & Spacer Kit

- Insufficient line rise/high reverse pressure
- Flare upshifts
- 6) 55209-04K

Valve spool diameters .474" & .441"

**Boost Valve** & Sleeve Kit

Helps cure:

- Insufficient line rise/high reverse pressure
- Flare upshifts
- 7 55211-01K




Helps cure:

- Reduced line pressure
- Gear ratio slip codes

Note: Requires tool kit F-55211-TL & the VB-FIX reaming fixture.

8) 55211-17K





Helps cure:


9

QUALULUM 7

- 3-2-1 Bump on coast downshifts
- Harsh/No engine braking in 1st, 2nd or 3rd

Note: Requires tool kit F-55211-TL17 & the VB-FIX reaming fixture.

(9) 55211-11K





- Loss of reverse
- TCC overheat

Note: Requires tool kit F-55211-TL & the VB-FIX reaming fixture.

(10) 55211-14K

3-4, 4-5 Safety Mode **Valve Kit** 

Fits any of 3 locations

Helps cure:

- 1-2 Bind-up, 3-4 Shift flare
- 4-5 Shift complaints, Clutch distress

Note: Requires tool kit F-55211-TL14 & the VB-FIX reaming fixture.

