Part Summary Data Sheet

41TE, 42LE, 42RLE, 45/545/68RFE

PART NUMBERS 92835-02K, 92835-18K, 92835-RM

COMPLAINT

Erratic/No TCC, 2nd Gear starts

SECONDARY COMPLAINTS

Low reverse switch code

Cause

Solenoid switch valve plugs cocking in the bore and/or bore wear at the switch valves

Correction

The replacement switch valve plugs feature a guide stem that connects the two halves and prevents valve cocking.

Solenoid Switch Valve Plug Kit

92835-02K

Replacement Plugs (2)

NOTE: Does not fit 41TE and 42RLE units with VLP

Oversized Solenoid Switch Valve Plug Kit


92835-18K

- Oversized Replacement Plugs (2)
- End Plug
- O-Ring

NOTE: Does not fit 41TE and 42RLE units with VLP. Patent No. 7,001,300

Reamer 92835-RM

Reamer



Common complaints with 41TE, 42LE/RLE and 45/545/68RFE transmissions include erratic or no torque converter clutch control, second gear starts and/or low reverse switch code. These can be caused by the solenoid switch valve plugs cocking in the bore and hanging up. Another cause of these complaints can be bore wear at the switch valves due to the cocking action and/or continuous oscillation of the plugs.

Sonnax offers the drop-in replacement solenoid switch valve plug kit 92835-02K for valve bodies which do not exhibit excessive bore wear. The 92835-18K kit is an oversized version of the kit for units with excessive wear and requires the 92835-RM reamer.

NOTE: For late-model 41TE and 42RLE VLP units with excessive wear, Sonnax also offers an oversized solenoid switch valve plug kit **92835-22K** that requires reamer **92835-RM22**.


Features & Benefits

- The two functional plugs have been redesigned to prevent cocking in the bore.
- One plug features a tightly toleranced thruhole that guides a stem on the mating plug.
- The 92835-18K kit includes an O-ringed end plug that positively seals the reamed bore.

You need this if...

©2010 Sonnax Industries, Inc.

A wet air test at either indicated port produces leakage from adjacent ports or past the plugs.





92835-02K Rev:- 92835-18K Rev:-, 92835-RM Rev:-, 92835-02K 08-16-10