
47RE ('97 CUMMINS)



Notes: Vehicle originally had fluid overheat temperature light on.