# 42-46-47RH/RE, A904, A727

PART NUMBER 22771-HDK

## COMPLAINT

**SECONDARY COMPLAINTS** 

## CAUSE

Excessive throttle valve and sleeve wear.

## CORRECTION

Sonnax repair kit both salvages valve body and restores throttle control.

# **Throttle Valve Kit**


### 22771-HDK

- 1 Throttle Valve
- 1 Throttle Plunger
- 1 Balance Spring
- 3 Spring Shims
- 1 Alternative TV Spring
- 1 Sleeve

**Note:** The modified TV spring should -never be installed alone. Always use at least one shim with spring.

## Shift timing concerns & throttle buzz

• Poor kickdown • Late 2-3 upshifts • Oversensitive 3-2 downshifts



## **Sonnax Part Summary**

Vehicles with 42-47RH/RE and A904-A727 transmissions may have problems with late 2-3 upshifts and oversensitive 3-2 downshifts. These complaints are often due to excessive wear between the throttle valve and throttle valve sleeve. Sonnax now offers the 22771-HDK throttle valve kit to address these problems.

#### **Features & Benefits**

- Hardened steel throttle valve kit restores worn valve body.
- Cures late 2-3 upshifts.
- Reduces oversensitive 3-2 downshifts.
- Works best in heavy-duty/towing applications.

