# Sonnax Breaks the Codes for Your 4765-E Valve Body

Puzzled by P0741 or P1311 codes? Sonnax has the answers.

5. 84754-40K

Oversized 1-2 (Forward) or Reverse Servo Boost Valve Kit

#### Helps cure:

- Delayed engagements
- Flared 1-2 shift
- Low reverse pressure

Note: Requires tool kits 84754-TL2

6. 84754-38K 3-4 Shift 84754-39K 4-3 Downshift

7. 84754-36K 2-3 Shift 84754-37K 3-2 Downshift

#### **Shift Valves**

#### Helps cure:

- Erratic or temperature-sensitive shifts
- 2nd gear start
- 2-3 shuttle shift
- No 3rd or 4th gear

# 8. 84596-02K




AFL Valve & Sleeve Kit FIXTURE

#### Helps cure:

- Code 1811
- Maximum adapt or long shift
- TCC slippage

Note: Requires tool kit F-84596-TL & the VB-FIX reaming fixture







### 1. 84754-30K

## **Boost Valve & Sleeve Assembly Kit**

#### Helps cure:

- Harsh reverse engagement
- Soft upshifts, especially 1-2
- Low line pressure, forward or reverse

## 2. **84754-44**

**Oversized Torque Signal Valve** 

## Helps cure:

- 1811 Code
- Poor or intermittent line rise
- Slip/shudder condition

Note: Requires tool kit 84754-TL44

## 84754-43K 84754-50K

## **TCC Apply Valve Kit**



# Helps cure:

- Code 741
- No lockup
- Falling out of lockup hot

Note: 84754-50K requires tool kit 84754-TL50 & reaming fixture VB-FIX.

## 84754-34K

**TCC Regulated Apply Valve Kit** 

#### Helps cure:

- TCC slip
- Code 741
- Ratio codes

Note: Requires tool kit 84754-TL3



Automatic Drive • P.O. Box 440 • Bellows Falls, Vermont 05101-0440 USA 800-843-2600 • 802-463-9722 • F: 802-463-4059 • www.sonnax.com • info@sonnax.com ©2008 Sonnax Industries, Inc