
47RE ('97)



Condition: Poor TCC, pump and switch valve control.

Correction: Sonnax Switch Valve 22771A-01.

Notes: With switch valve imbalance, valve double-bounces on TCC release, poor switch action.