

PRODUCT INFORMATION


700-R4

Part No. 77731

1 Complete Planetary

Unit Price: 1-49 \$42.50 Unit Price: 50-249 \$38.50 Unit Price: 250+ \$36.00

Rear Planetary Assembly



SONNAX PART SUMMARY

Planetary assembly wear is generally caused by insufficient lube oil and/or excessive clearances. Lack of lube causes excessive heat in the pinion gear area and causes the roller bearings to gall the gear bores and pinion pins. If there is excessive thrust washer wear or end play, the roller bearings can run without fully contacting the gear bore, causing premature failure of the assembly.

©1999 Sonnax Industries, Inc.

TSInSto\77731(info)699: Rev A