PART NUMBER 85701-01

Neutralizes on 3-4 shift


A broken cushion washer that gets stuck in the overdrive servo bore will not allow band apply

Replace the broken cushion washers with these servo cushion washers which are now available separately.

Servo Belleville Cushion Washer

85701-01

2 Servo Cushion Washers



Sonnax Part Summary

This servo cushion washer is not serviced as an individual part by the OEM. In the past it was necessary to purchase an entire servo assembly. Sonnax now offers a replacement servo cushion washer 85701-01.

