# Sonnax Has What's Needed

# for the AX4N/4F50N Unit!

## *I.* **96206-07K** U.S. Patent No. 6,736,747

#### **Forward Control Valve**

#### Helps cure:

- No forward
- No 4th gear

Note: Use of bore sizing tool 96206-BST is not required but is highly recommended.

#### 2. 96201-05

#### **Manual Valve**

#### Helps cure:

- Delayed forward engagement
- Burned forward clutch

### 3. 96201-18

## **Pump Shaft Sleeve**

#### Helps cure:

- Oil loss
- Worn sleeve

## 4. 96201-21K

## **Oversized Solenoid** Regulator Valve Kit



- No converter clutch apply
- TCC cycle or surge

Note: Requires tool kit 96201-TL2.

## 5. **96201-23K**

## **Oversized Converter Regulator Valve Kit**



- Codes 628, 1741 & 1744
- TCC cycling or surge

Note: Requires either tool kit 96201-TL3 or F-96201-TL23 & the VB-FIX reaming fixture.

#### 6. 96206-10K

## **Oversized Pressure** Regulator Valve Kit

#### Helps cure:

- Line pressure instability
- Pump noise or rotor & cover damage

Note: Requires tool kit 96206-TL2.

# 7. O-Ring Style:

96201-01K All except 3.0L 96201-12K 3.0L 12-Valve

Factory Style: 96201-08K All except 3.0L 96201-13K 3.0L 12-Valve

## **Reverse Boost Valve** and Sleeve Kits

#### Helps cure:

- Flare 1-2 or 2-3 upshifts
- Non-adjustable throttle pressure

#### 8. 96206-05K

# Oversized Bypass **Clutch Control Valve Kit**

#### Helps cure:

- TCC apply & release problems
- Excess TCC slip RPM

Note: Requires tool kit 96206-TL.



## 10.36948-20K

### **Oversized Accumulator Pressure Control Valve**

12.

## Helps cure:

- Harsh shift complaints
- Harsh 1-2, soft shifts

Note: Requires tool kit 36948-TL.







Automatic Drive • P.O. Box 440 • Bellows Falls, Vermont 05101-0440 USA 800-843-2600 • 802-463-9722 • F: 802-463-4059 • www.sonnax.com • info@sonnax.com