
## 4L80-E ('99)



**Correction:** Low pump rpm, engine often stumbles or stalls at this condition. Update TCM or improve pressure regulator flow.