
46RH, RE (A518) ('95)



Event: 0 gpm flow in all ranges.

Condition: Plugged radiator after flush machine, repeat converter failure.

Correction: See Chart A on page 71.

Notes: Road test felt fine even with plugged cooler.