# Sonnax Has the 5L40-E Covered!

Fix these common problems wherever they occur



**Pressure Regulator Valve & Sleeve Kit** 

- Worn Pressure Regulator valve bore
- Low pressure
- Gear ratio codes

Note: Requires tool kit 55211-TL8

#### 2. **55209-01K**

**Boost Valve & Spacer Kit** 

#### Helps cure:

- Insufficient line rise
- High reverse pressure
- Flare upshifts







# Reverse Lockout Kit



- Loss of reverse
- TCC overheat
- Burned reverse clutch

Note: Requires tool kit F-55211-TL & the **VB-FIX** reaming fixture.



### 4. 55211-04K

#### **TCC Regulator Valve** & Sleeve Kit

#### Helps cure:

- TCC slip and ratio codes
- Transmission/converter overheat
- Delayed or no reverse

Note: Requires tool kit F-55211-TL4 & the VB-FIX reaming fixture.

## 5. **55211-01K AFL Valve & Sleeve Kit**


#### Helps cure:

- Reduced line pressure
- Gear ratio slip codes
- 2nd gear starts, loss of 4th/5th gear

Note: Requires tool kit F-55211-TL











Automatic Drive • P.O. Box 440 • Bellows Falls, Vermont 05101-0440 USA 800-843-2600 • 802-463-9722 • F: 802-463-4059 • www.sonnax.com • info@sonnax.com ©2009 Sonnax Industries, Inc



Fluid Pump Assembly