
## 4T65-E 2000 Impala



**Condition:** Normal. We suggest use of Snap-On Vantage<sup>TM</sup> to capture TCC control as there is a very slight change.

**Correction:** Normal, well defined and active flow.