	Vehicle Complaints/Part Type	Product Name	Part Number	Illustration Number	Product/Application Details	HP or HD Use	Required Tool	Required Fixture
	TCC/Lockup							
Pressure Problems	No lockup, Falling out of lockup hot, Fluid blows out fill tube	TCC Apply Valve Kit	77805-K		Steel valve with Teflon® seal			
	3-4 Clutch failure, Excessive pump noise, Low line pressure, Clutch slippage	Oversized Pressure Regulator Valve	77917-06				77917-TL or 77917-TLC	
	Burned 3-4 clutch, Shortened band life, Soft/Slide shifts	TV Boost Valve Kit	77917-01K		.423" Bore dia., 0-Ring style			
		TV Boost Valve Kit	77917-471		.471" Bore dia., 0-Ring style			
		TV Boost Valve Kit	77917-02K		.423" Bore dia., "Factory" style			
		TV Boost Valve Kit	77917-03K		.471" Bore dia., "Factory" style			
	Poor reverse boost, Delayed reverse, Low line pressure	Reverse Boost Valve Kit	K77898		Large ratio, 0-Ring style	Y		
		Reverse Boost Valve Kit	K77898A		Large ratio, "Factory" style			
	1-2 Bang (light throttle), End bump shift, Shortened 3-4 band life	Accumulator Valve Train Kit	77777M-K		Heavy weight vehicles			
T S		Accumulator Valve Train Kit	77777L-K		Medium weight vehicles			
Shift Concer	Soft 1-2, Poor downshift & upshift control, Sticky/Erratic throttle valve operation, Poor line rise	Throttle Valve Sleeve Kit	65754-01K		.357" dia.			
		Throttle Valve Sleeve Kit	65754-02K		.390" dia.			
		Throttle Valve Sleeve Kit	65754-03K		.430" dia.	Y		
	Common or Repeat Failure							
	Burned clutches & bands, Poor shift quality	Pinless Accumulator Piston Kit	77998-03K		Includes, piston, seal & balls, for 3-4 location only	Y		
	Accumulator part	Oversized Accumulator Pin & Reamer Kit	77999-02K		Starter kit, includes 10 pins & reamer	Y		
	Accumulator part	Oversized Accumulator Pin	77999		Includes 4 pins only	Y	77999-02K	
	Pump part	Pump Vane	1280		Torrington OEM			
cts	Pump part	Pump Vane Guide	4734		10 Vane, plastic			
를	Pump part	Pump Slide Pivot Pin	65797		5/Bag			4
풑	Pump part	Pump Bushing	77005T		Teflon® coated	Y		
Other	Stator Support Shaft	Stator Support Shaft	65917S		27 External splines, heat treated			4
	TV Cable part	Universal TV Cable Repair Kit	77872-02K					\perp
	TV Cable part	TV Cable Corrector Kit	AS1-01K					
	TV Cable part	TV Cable Corrector Bracket Kit	AS2-02K		For Holley carburetors	Y		
	TV Cable part	TV Cable Corrector Bracket Kit	AS3-03K		For Edelbrock/Carter carburetors	Y		
ols	Tool	Reamer & Drill Jig	77917-TL		For oversized pressure regulator valve kits 77917-06 & 77917-07			
P	Tool	Carbide Reamer & Drill Jig	77917-TLC		For oversized pressure regulator valve kits 77917-06 & 77917-07			

					Illustra				Required Fixture
		Performance Enhancement	Product Name	Part Number	Num	mber	Product/Application Details	Required Tool	Fixture
		-A- Valve Body							
	#	-	TV Plunger Spring	77968-01K			5/Bag		
		Highest OEM TV boost ratio, Maximum line rise	TV Boost Valve Kit	77917-500			.500" Bore dia., O-Ring style		
			TV Boost Valve Kit	77917-04K			.500" Bore dia., "Factory" style		
ą,	┿틀	Increases base line pressure	Elevated Pressure Regulator Spring	77917-08					
anc		Maintains high pump volume position at high RPM	Pump Slide Spring	77722-01K			Replaces 2 OEM springs, 5/bag		
Ĕ		Higher & more stable pump output	Pump Spring Shim	77917-RV			10/Bag		
皇		-C- Servo/Band							
8		Maximizes holding power for firmest 1-2, 2-3 shifts	"Super Hold" Servo	K65703			Purple anodized cover		4
High	9		"Super Hold" Servo	K65703-1			Non-anodized cover		
-		Wider, thicker band for improved 1-2 shifts	Alto Extra Wide Intermediate Band	S043961			Red material		
j		-D- Internal							
	÷	Improves clutch apply & durability	Direct Clutch Piston Insert	65772J-01					
		-E- Case							
	#	Plugs unused speedo gear hole while maintaining output bushing lube	Speedometer Hole Plug Kit	35922-01K					

Red Part Number = New in Vol. 8