## G4A-EL, GF4A-EL, F4A-EL, F4EAT

PART NUMBERS 71846-01K, 74846-01K

# COMPLAINT

SECONDARY COMPLAINTS

# CAUSE

Worn boost valve sleeves allow EPC, TV boost or reverse pressures to cross leak into exhaust.

## Correction

These replacement boost valve kits are hardened and anodized to prevent wear and are tightly toleranced to restore the hydraulic integrity of the circuits.

### **Boost Valve Kits**

G4A-EL

71846-01K

with TV Cable

- 1 Boost Valve
- 1 Boost Sleeve
- 1 Boost Plug

GF4A-EL, F4A-EL (Mazda), F4EAT (Ford)

74846-01K No 7

No TV Cable/with Electronic Transmission


- 1 Boost Valve
- 1 Boost Sleeve

The application listed above is meant as a guide only.

Be sure to measure original valve and compare dimensions before purchasing.

### Low line rise

• Low reverse boost and shudder • Delayed reverse • Poor 1-2 shift



#### **Sonnax Part Summary**

Vehicles with a G4A-EL or GF4A-EL, F4A-EL, or F4EAT transmission may have problems with low line rise or low reverse boost. These problems can be caused by worn boost valve sleeves that allow EPC (GF4A-EL F4A-EL, F4EAT), TV boost (G4A-EL F4A-EL, F4EAT), or reverse pressures to cross leak or leak to exhaust. Sonnax has developed replacement boost valve kits for both the G4A-EL, 71846-01K, and the GF4A-EL, F4A-EL, and F4EAT, 74846-01K.

#### **Features & Benefits**

©2006 Sonnax Industries, Inc.

- The GF4A-EL boost valve is made from anodized aluminum, and the sleeve is manufactured from high-quality aluminum to resist wear.
- The **74846-01K** GF4A-EL kit has been modified to fit the F4A-EL and F4EAT applications, and allows for more responsive EPC pressure.

