

PART NUMBERS 56947J-01K. -03K

High TCC slip RPM at increasing load

SECONDARY COMPLAINTS

The plunger force is transferred onto the inner modulator valve. When the sleeve wears, the converter apply slippage increases.

The Sonnax assemblies restore proper hydraulic clearances so fluid pressure can position the TCC modulator valve to fully apply lockup. The increasedd ratio assembly provides a firmer and quicker lockup feel.

TCC Modulator Sleeve & Plunger Assemblies

56947J-03K

Increased Ratio

56947J-01K

OEM Ratio


Each kit includes the following

1 Sleeve

1 Valve

Note: The valve bore inward of this TCC modulator sleeve wears rapidly. Always inspect for bore wear at the largest spool of the inner valve.

• Slip codes • Elevated fluid temperature



Sonnax Part Summary

Some common complaints associated with a 5R55W/S are high TCC slip RPMs under increasing loads, slip codes, and converter apply or release concerns. These complaints are often caused by wear at the ID of the TCC modulator plunger valve sleeve, due to constant oscillation by the pulse width modulated TCC solenoid. This plunger valve positions the TCC modulator valve, which feeds line to the apply circuit, which controls slip rate. Wear of the sleeve will allow the TCC slip rate to continue to rise, and could prevent full lockup. The Sonnax assemblies restore hydraulic integrity to the TCC solenoid circuit with precisely toleranced parts. The elevated modulated pressure will not raise apply pressure to the point of TCC piston fatigue, and will result in firmer TCC apply and reduced slip RPM in heavier use applications.

Features & Benefits

- Increased ratio provides a firmer and quicker lockup feel.
- OEM stock ratio restores original lockup feel.
- Precisely toleranced parts restore hydraulic integrity.
- Hard-coat anodized aluminum valves resists wear.
- High-grade aluminum sleeves are extremely wear-resistant.

