PART NUMBERS 15741-18K, F-15741-TL18

Complaint

DTC's P0734, P0735 or P0729

SECONDARY COMPLAINTS

• Slippage or shock on kickdown • Slippage in steady driving 4, 5 or 6th gear

Cause

High and/or low pressure in the solenoid modulator circuits can cause DTC codes and drivability complaints. Wear at the inboard end causes excessive feed pressure. This floods the solenoids, reduces reaction time, resulting in harsh shifting and high line pressure. Wear at outboard and mid-section reduces solenoid modulator pressure. This loss has the most effect on engagements and boost oil for line pressure rise.

Correction

The Sonnax wear resistant sleeve and valve corrects circuit pressure loss and restores control over solenoid modulator valve function.

Solenoid Modulator Valve Kit

15741-18K Use In Two Locations

- 1 Solenoid Modulator Valve
- 1 Solenoid Modulator Sleeve
- 1 Spring
- 1 Plug Used in Upper VB #2 Only

F-15741-TL18

- 1 Reamer
- 1 Guide Pin
- 1 Reamer Jig




Note: Fits BMW 6F21WA & VW/Audi 09G, 09K, 09M.

F-15741-TL29PL

- 1 Adapter Plate
- 3 Assorted Screws

Note: Mounting plate **F-15741-TL29PL** is required for reaming Upper Valve Body #2.



Features & Benefits

- The hard-coat anodized aluminum valve resists wear and has added annular grooves for better centering in the bore.
- The highly wear-resistant sleeve and lengthened front valve spool provide 75% more sealing contact area.
- This kit includes a new end plug and spring for proper calibration.

You need this if...

Either a Wet Air Test or a Vacuum Test in the locations shown, result in leakage. A vacuum test must hold a minimum of 18".

