**PART NUMBER 36946-05K** 

# 1-2 Accumulator Spring Set

## 36946-05K

5 Outer Springs 5 Inner Springs


Also available:

## 39833-01K & -TL

Oversized Modulator Valve & Reamer System

## K36528R

High Performance R-Code Servo Kit



#### Installation Instructions

If either of the 1-2 accumulator springs are broken or measure less than 1 5/16" long, then the spring set needs to be replaced (do not stretch out existing springs since they will quickly collapse again in service). Discard the damaged springs and replace with the Sonnax springs 36946-05K.

Note: A burned clutch band may also be caused by problems other than the 1-2 accumulator spring. To check for other problem sources, perform the Wet Air Tests indicated in the diagram below.

