Part Summary

Rear Clutch Inner Lip Seal

Part No. 3647-01

Viton® Seals (5)

Chrysler 46-47RH/RE, 48RE



Delayed or no forward engagement in Chrysler 46-47RH/RE and 48RE units is often caused by a shrunken or deteriorated inner lip seal in the rear (forward) clutch piston. The Viton® material and improved design of the Sonnax rear clutch inner lip seal **3647-01** provides better sealing and enhanced seal life.

Features & Benefits

- Improved design features a longer/beefier lip
- Seal material upgraded to Viton® compound

NOTE: Clutch drum surface should be prepared with 600 grit Wet/Dry paper and seal. Seal should be well lubricated prior to installation.