
4T60, 4T60-E '96 (NOT EC3)



Correction: Sonnax TCC Apply Valve **84754-22K** or **84754-16K** and required reamer.

Notes: Minimal to no ramp while watching TCC apply/enable signal on scanner.