Site Assessment Report NRLA-5521

Property	7 Riverbend Road, North Lismore NSW 2480
Inspection	8 October 2026, 10:00am
Instructed by	Halcyon General Insurance - claim CLM-2026-0461290

Source of water: Clear tide marks and silt deposits at 38-42cm above floor level on all ground-floor walls, consistent with the same level on the exterior of the dwelling, the garage and the rear fence line. Debris lines run from the rear boundary, which adjoins Leycester Creek, toward the house.

Roof and building envelope: Roof sheeting, flashings, gutters and ceilings inspected - no storm damage, no wind damage, no ceiling staining. No evidence of rainwater entry from above.

Opinion on cause: The damage was caused by water that overflowed from the normal confines of Leycester Creek following prolonged heavy rainfall, inundating normally dry land and entering the dwelling at ground level. In our opinion this meets the policy definition of flood. We found no damage attributable to storm (wind) or rainwater entry.

Safety: Electrical safety check recommended before power is restored to ground-floor circuits.

Damage observed	Estimated cost (AUD)
Carpet and underlay 32 m2	$3,650
Plasterboard, insulation, skirting (lower walls)	$5,400
Contents - furniture and appliances	$6,550
Clean-up and silt removal	$850
Total estimate	$16,450