Direction "from"

Key	Value	Meaning
concentration	0 ... 2550 [ppm], step 10	Concentration (linear), increment = 10 ppm
humidity	0 ... 100 [%], step 0.5	Rel. Humidity (linear), 0.5 % = 1 bit
temperature	0 ... 51 [°C], step 0.2	Temperature (linear), increment = 0.2 °C