ERRATA CSMB12 / APS12SLK

with MC9S12DT256 MCU Installed:

This ERRATA sheet applies to the CSMB12 / APS12SLK module with the MC9S12DT256 MCU installed. Please read this document in its entirety before continuing. Important information on configuring and using module is included.

CodeWarrior for HC(S)12 requires a service pack update before use with the CSMB12 / APS12SLK module with a MC9S12DT256 MCU installed. Please download and install the CW12_V4_6_HCS12_DT256_SP service pack before using the CSMB12 / APS12SLK module.

The required service pack may be downloaded from the Freescale web site at www.freescale.com. To find the service pack simply enter "DT256 Service Pack" into the Keyword search box located in the upper right corner of Freescale.com web site.

The required service pack may also be downloaded from the Axiom Manufacturing web site at www.axman.com. To access the DT256 Service Pack, select the Support link a the top of the page. Then select Educational -> APS12SLK (CSMB12) Module.

After downloading and installing the service pack, follow the Quick Start Guide to get started using the CSMB12 / APS12SLK module quickly.

Please contact Freescale Technical Support for help installing the DT256 Service Pack if necessary. Refer to the Technical Information Center card included with this board for contact details.



