
The AVR-CDC Evaluation Report (ATmega48)

Test Scheme Connection



8N1, FlowControl: none No other USB devices connected to the target Host Controller on PC No.2.

- Procedure
 Transmit text data (670kB) from PC1 to PC2.
 Transmit the received text on PC2 back to PC1.
 Compare the returned text.
 Repeat (1)-(3) 3 times.

2. Result - Rx Interrupt

Model PC No.2)	Vendor	PC Spec.	OS / Driver (Version)	USB Host Controller Driver	USB Interface		USB Host Controller	Result	Max. Baudrate (Half duplex)	Max. Baudrate (Full duplex)	Cause
4GER	AOpen	Pentium4	KNOPPIX 3.7	usb-uhci.c Rev 1.275	on-board	SouthBridge	Intel 845G(ICH4)	OK	38.4kbps	*5	
		2.4GHz RAM 512MB	Kernel 2.4.27	usb-ohci.c v5.3	RATOC REX-PCIU3	PCI	NEC uPD720101	OK	57.6kbps	*5	
				usb-uhci.c Rev 1.275	KurotoShiko USB2.0V3-PCI	PCI	VIA VT6202	OK	38.4kbps	*5	
			acm.c: v0.21	usb-uhci.c Rev 1.275	KurotoShiko USB2.0V5-PCI	PCI	VIA VT6212L	OK	38.4kbps	*5	
				usb-ohci.c v5.3	ALI USB2ALI1-B01	PCI	ALi M5273	OK	57.6kbps	*5	
				uhci.c v1.1	IODATA CBUS2L	CardBus	VIA VT6212L	OK	38.4kbps	*5	
				usb-ohci.c v5.3	UnionBros UBH004	CardBus	OPTi 82C861				
								OK	57.6kbps	*5	
				usb-ohci.c v5.3	RATOC REX-CBU2X	CardBus	NEC uPD720101	OK	57.6kbps	*5	
				usb-ohci.c v5.3	BUFFALO IFC-USB2CB	CardBus	NEC uPD720100A	OK	57.6kbps	*5	
			KNOPPIX 5.0.1 Kernel 2.6.17	uhci_hcd.c v3.0	on-board	SouthBridge	Intel 845G(ICH4)	NG *1	•	•	Low speed bulk transfe prohibited in uhci_hcd.o
				ohci_hcd.c 2005 April 22	RATOC REX-PCIU3	PCI	NEC uPD720101	OK	19.2kbps	*5	
			usb-acm : v0.25	uhci_hcd.c v3.0	KurotoShiko USB2.0V3-PCI	PCI	VIA VT6202	NG *1	-	-	Low speed bulk transfe prohibited in uhci_hcd.
				uhci_hcd.c v3.0	KurotoShiko USB2.0V5-PCI	PCI	VIA VT6212L	NG *1	-	-	Low speed bulk transfe prohibited in uhci_hcd.
				ohci_hcd.c 2005 April 22	ALI USB2ALI1-B01	PCI	ALi M5273	OK	19.2kbps	*5	
		l		uhci_hcd.c v3.0	IODATA CBUS2L	CardBus	VIA VT6212L	NG *1	10.2000		Low speed bulk transfe
				_							prohibited in uhci_hcd.
				ohci_hcd.c 2005 April 22	UnionBros UBH004	CardBus	OPTi 82C861	OK	19.2kbps	*5	<u> </u>
				ohci_hcd.c 2005 April 22	RATOC REX-CBU2X	CardBus	NEC uPD720101	OK	19.2kbps	*5	
				ohci_hcd.c 2005 April 22	BUFFALO IFC-USB2CB	CardBus	NEC uPD720100A	OK	19.2kbps	*5	
			Debian 3.1_rc2	uhci_hcd.c with Patch	on-board	SouthBridge	Intel 845G(ICH4)	OK *2	38.4kbps	*5	
			Kernel 2.6.8-2-386	ohci_hcd.c 2004 Feq 02	RATOC REX-PCIU3	PCI	NEC uPD720101	OK	19.2kbps	*5	1
			usb-acm : v0.23	uhci_hcd.c with Patch	KurotoShiko USB2.0V3-PCI	PCI	VIA VT6202	OK *2	38.4kbps	*5	Transmission may not begun rarely.
				uhci_hcd.c with Patch	KurotoShiko USB2.0V5-PCI	PCI	VIA VT6212L	OK *2	38.4kbps	*5	Transmission may not begun rarely.
				ohci_hcd.c 2004 Feq 02	ALI USB2ALI1-B01	PCI	ALi M5273	OK	19.2kbps	*5	Out-data (USB->RS23 corrupts very rarely.
				uhci_hcd.c with Patch	IODATA CBUS2L	CardBus	VIA VT6212I	OK *2	38.4kbps	*5	,,
				ohci_hcd.c 2004 Feq 02	UnionBros UBH004	CardBus	OPTi 82C861	OK 2	19.2kbps	*5	
					RATOC REX-CBU2X	CardBus	NEC uPD720101				
				ohci_hcd.c 2004 Feq 02				OK	19.2kbps	*5	
				ohci_hcd.c 2004 Feq 02	BUFFALO IFC-USB2CB	CardBus	NEC uPD720100A	OK	19.2kbps	*5	
			Windows 2000 SP4	[UHCI]	on-board	SouthBridge	Intel 845G(ICH4)	OK	38.4kbps	*3	
				[OHCI]	RATOC REX-PCIU3	PCI	NEC uPD720101	oĸ	57.6kbps	*3	
				[UHCI]	KurotoShiko USB2.0V3-PCI	PCI	VIA VT6202	OK	38.4kbps	*3	
				IUHCII	KurotoShiko USB2.0V5-PCI	PCI	VIA VT6212L	OK	38.4kbps	*3	
				[OHCI]	ALI USB2ALI1-B01	PCI	ALi M5273	OK	57.6kbps	*3	
				[UHCI]	IODATA CBUS2L	CardBus	VIA VT6212L				
		1			UnionBros UBH004	CardBus	OPTi 82C861	OK	38.4kbps	*3	
		1		[OHCI]				OK	57.6kbps	*3	ļ
				[OHCI]	RATOC REX-CBU2X	CardBus	NEC uPD720101	OK	57.6kbps	*3	
				[OHCI]	BUFFALO IFC-USB2CB	CardBus	NEC uPD720100A	OK	57.6kbps	*3	
			Windows XP SP2	[UHCI]	on-board	SouthBridge	Intel 845G(ICH4)	OK	57.6kbps	57.6kbps	
				[OHCI]	RATOC REX-PCIU3	PCI	NEC uPD720101	OK	115.2kbps	57.6kbps	
				[UHCI]	KurotoShiko USB2.0V3-PCI	PCI	VIA VT6202	OK	57.6kbps	57.6kbps	1
				[UHCI]	KurotoShiko USB2.0V5-PCI	PCI	VIA VT6202 VIA VT6212L	(OK)	57.6kbps	57.6kbps *4	
				IOHCII	ALI USB2ALI1-B01	PCI	ALi M5273	OK	57.6kbps	57.6kbps 4	
			I	,	IODATA CBUS2L	CardBus	VIA VT6212L				
		1		[UHCI]				(OK)	57.6kbps	57.6kbps *4	Tourstown b
				[OHCI]	UnionBros UBH004	CardBus	OPTi 82C861	OK	115.2kbps	38.4kbps	Teraterm hangs at a h speed full duplex trans
		l		[OHCI]	RATOC REX-CBU2X	CardBus	NEC uPD720101	OK	115.2kbps	115.2kbps	
		Ì		[OHCI]	BUFFALO IFC-USB2CB	CardBus	NEC uPD720100A	OK	115.2kbps	115.2kbps	
VL2120	SOTEC	Mobile Celeron	Windows XP SP2	[OHCI]	on-board		SiS7001	OK	57.6kbps	57.6kbps	
		1.2GHz		[UHCI]	IODATA CBUS2L	CardBus	VIA VT6212L	(OK)	19.2kbps	9600bps *4	
		RAM:384MB		[OHCI]	UnionBros UBH004	CardBus	OPTi 82C861	ОК	57.6kbps	9600bps	Teraterm hangs at a h speed (>57.6Kbps) ful duplex transfer.
				[OHCI]	RATOC REX-CBU2X	CardBus	NEC uPD720101	OK	57.6kbps	57.6kbps	
				[OHCI]	BUFFALO IFC-USB2CB	CardBus	NEC uPD720101	OK	57.6kbps	57.6kbps	
				[OTIO]	BULLATO ILC-09D5CR	Odlubus	NEC UPD/20100A	UN	37.0KDPS	37.0KDPS	
	1	I	1		on-board	SouthBridge	Intel 440ZXM	NG		*3	IN response stops bed
opad X20		Pentium3	Windows 2000 SP4	[UHCI]							

^{*1 :} may work if uhci_q.c is modified (not tested).

*2 : usb_uhci.c (v2.2) has been modified to enable bulk transfer.

*3 : in Windows2000, it seems that IN request is not issued while retrying OUT request.

*4 : Data corrupts at OUT direction (USB-xRS23C) in full duplex transfer, not due to baudrate.

*5 : minicom can not receive data during transmission.

3. Result - Rx Polling

PC No.1 : NT-5000 (EPSON DIRECT) Mobile Pentium4 2GHz, RAM512MB, Windows2000 SP4

Model (PC No.2)	Vendor	PC Spec.	OS / Driver (Version)	USB Host Controller Driver	USB Interface		USB Host Controller	Result	Max. Baudrate (Half duplex)	Max. Baudrate (Full duplex)	Cause
MX4GER	AOpen	Pentium4	KNOPPIX 3.7	usb-uhci.c Rev 1.275	on-board	SouthBridge	Intel 845G(ICH4)				
		2.4GHz	Kernel 2.4.27	usb-ohci.c v5.3	RATOC REX-PCIU3	PCI	NEC uPD720101				
		RAM 512MB		usb-uhci.c Rev 1.275	KurotoShiko USB2.0V3-PCI	PCI	VIA VT6202				
			acm.c : v0.21	usb-uhci.c Rev 1.275	KurotoShiko USB2.0V5-PCI	PCI	VIA VT6212L				
				usb-ohci.c v5.3	ALI USB2ALI1-B01	PCI	ALi M5273				
				uhci.c v1.1	IODATA CBUS2L	CardBus	VIA VT6212L				
				usb-ohci.c v5.3	UnionBros UBH004	CardBus	OPTi 82C861				
				usb-ohci.c v5.3	RATOC REX-CBU2X	CardBus	NEC uPD720101				
				usb-ohci.c v5.3	BUFFALO IFC-USB2CB	CardBus	NEC uPD720100A				
			KNOPPIX 5.0.1	uhci_hcd.c v3.0	on-board	SouthBridge	Intel 845G(ICH4)				
			Kernel 2.6.17	ohci_hcd.c 2005 April 22	RATOC REX-PCIU3	PCI	NEC uPD720101				
				uhci_hcd.c v3.0	KurotoShiko USB2.0V3-PCI	PCI	VIA VT6202				
			usb-acm : v0.25	uhci_hcd.c v3.0	KurotoShiko USB2.0V5-PCI	PCI	VIA VT6212L				
				ohci_hcd.c 2005 April 22	ALI USB2ALI1-B01	PCI	ALi M5273				
				uhci_hcd.c v3.0	IODATA CBUS2L	CardBus	VIA VT6212L		 		
				ohci_hcd.c 2005 April 22	UnionBros UBH004	CardBus	OPTi 82C861				
			1	ohci_hcd.c 2005 April 22	RATOC REX-CBU2X	CardBus	NEC uPD720101				
				ohci_hcd.c 2005 April 22	BUFFALO IFC-USB2CB	CardBus	NEC uPD720101		1		
				01101_1100.0 2000 April 22	DOLLATO IL C-000520D	Galubus	14LO UF D720100A		-		
		1	Dobion 2.1 ==2	luboi had a with Datah	on board	CouthDelda -	Intel 845G(ICH4)				
			Debian 3.1_rc2 Kernel 2.6.8-2-386	uhci_hcd.c with Patch	on-board	SouthBridge	. ,				
			Kerner 2.0.0-2-300	ohci_hcd.c 2004 Feq 02	RATOC REX-PCIU3	PCI	NEC uPD720101				
			usb-acm : v0.23	uhci_hcd.c with Patch	KurotoShiko USB2.0V3-PCI	PCI	VIA VT6202				
			400 dom : V0.20	uhci_hcd.c with Patch	KurotoShiko USB2.0V5-PCI	PCI	VIA VT6212L				
				ohci_hcd.c 2004 Feq 02	ALI USB2ALI1-B01	PCI	ALi M5273				
				uhci_hcd.c with Patch	IODATA CBUS2L	CardBus	VIA VT6212L				
				ohci_hcd.c 2004 Feq 02	UnionBros UBH004	CardBus	OPTi 82C861				
				ohci_hcd.c 2004 Feq 02	RATOC REX-CBU2X	CardBus	NEC uPD720101				
				ohci_hcd.c 2004 Feq 02	BUFFALO IFC-USB2CB	CardBus	NEC uPD720100A				
			Windows 2000 SP4	[UHCI]	on-board	SouthBridge	Intel 845G(ICH4)				
				[OHCI]	RATOC REX-PCIU3	PCI	NEC uPD720101				
				[UHCI]	KurotoShiko USB2.0V3-PCI	PCI	VIA VT6202				
				[UHCI]	KurotoShiko USB2.0V5-PCI	PCI	VIA VT6212L				
				[OHCI]	ALI USB2ALI1-B01	PCI	ALi M5273				
				[UHCI]	IODATA CBUS2L	CardBus	VIA VT6212L				
				[OHCI]	UnionBros UBH004	CardBus	OPTi 82C861				
				[OHCI]	RATOC REX-CBU2X	CardBus	NEC uPD720101				
				[OHCI]	BUFFALO IFC-USB2CB	CardBus	NEC uPD720100A				
			Windows XP SP2	[UHCI]	on-board	SouthBridge	Intel 845G(ICH4)	OK	38.4kbps	19.2kbps	
		1		[OHCI]	RATOC REX-PCIU3	PCI	NEC uPD720101	OK	38.4kbps	19.2kbps	
		ĺ	1	[UHCI]	KurotoShiko USB2.0V3-PCI	PCI	VIA VT6202	OK	38.4kbps	19.2kbps	
		ĺ	1	[UHCI]	KurotoShiko USB2.0V5-PCI	PCI	VIA VT6202 VIA VT6212L	OK	38.4kbps	19.2kbps	
		1	1	[OHCI]	ALI USB2ALI1-B01	PCI	ALi M5273	OK	38.4kbps	19.2kbps	
		ĺ	1	[UHCI]	IODATA CBUS2L	CardBus	VIA VT6212L	OK	38.4kbps	19.2kbps	
		1	1	IOHCII	UnionBros UBH004	CardBus	OPTi 82C861	OK	38.4kbps 38.4kbps		
		1	1	[OHCI]	RATOC REX-CBU2X	CardBus	NEC uPD720101	OK	•	19.2kbps	
		1	1						38.4kbps	19.2kbps	
		1	1	[OHCI]	BUFFALO IFC-USB2CB	CardBus	NEC uPD720100A	OK	38.4kbps	19.2kbps	
	00756		W	rauan	L		0.00000				
WL2120	SOTEC	Mobile Celeron	Windows XP SP2	[OHCI]	on-board	<u> </u>	SiS7001	OK	19.2kbps	19.2kbps	
		1.2GHz	1	[UHCI]	IODATA CBUS2L	CardBus	VIA VT6212L	(OK)	19.2kbps	*2	
		RAM:384MB	1	[OHCI]	UnionBros UBH004	CardBus	OPTi 82C861	OK	19.2kbps	19.2kbps	
				[OHCI]	RATOC REX-CBU2X	CardBus	NEC uPD720101	OK	19.2kbps	19.2kbps	
				[OHCI]	BUFFALO IFC-USB2CB	CardBus	NEC uPD720100A	OK	19.2kbps	19.2kbps	
	1	I	I								-
hinkpad X20	IBM	Pentium3 700MHz	Windows 2000 SP4	[UHCI]	on-board	SouthBridge	Intel 440ZXM	OK	19.2kbps	*1	

^{*1 :} In Windows2000, it seems that IN request is not issued while retrying OUT request.
*2 : Data corrupts at IN process in full duplex transfer, not due to baudrate.

4. Comment
(1) Windows Driver and its Version
Windows 2000 SP4

[OHCl Host Driver]
openhci.sys 5.00.2195.6675
usbd.sys 5.00.2195.6659
usbhub.sys 5.00.2195.6689
usbui.dll 5.00.2134.1

[UHCI Host Driver]

uhcd.sys 5.00.2195.6655 usbd.sys 5.00.2195.6658 usbhub.sys 5.00.2195.6689 usbui.dll 5.00.2134.1

[Serial Port Driver] usbser.sys 5.00.2195.6655

Windows XP SP2

[OHCI Host Driver] usbhub.sys 5.1.2600.2180 usbohci.sys 5.1.2600.2180 usbport.sys 5.1.2600.2180 usbui.dll 5.1.2600.2180

[UCHI Host Driver] usbhub.sys 5.1.2600.2180 usbport.sys 5.1.2600.2180 usbuhci.sys 5.1.2600.2180 usbui.dll 5.1.2600.2180

[Serial Port Driver] usbser.sys 5.1.2600.2180

(2) Linux: CDC device is recognized as /dev/ttyACM0