#### **YoLink Device Service v2.1.12**

- Reduce instantaneous hub load when polling devices
- Return name of device that MQTT message was passed to back to MQTT Listener for debugging

## **SpeakerHub v2.0.5 (YS1604-UC)**

- Prevent Service app from waiting on device polling completion
- Add warnings for unsupported commands instead of causing an error

# Temperature Humidity Sensor v2.0.7 (YS8003-UC) and X3 SMART TEMPERATURE & HUMIDITY SENSOR (YS8006-UC)

- Prevent Service app from waiting on device polling completion
- Add temperature history tracking attributes: "highDay", "lowDay", "highest", "lowest", "highestDate", "lowestDate"

# GarageDoor Device v2.0.6 (YS4906-UC)

- Prevent Service app from waiting on device polling completion
- Fixed MQTT message processing

# Flex Fob v2.0.6 (YS3604-UC), Flex Fob v2 (YS3604-UC), On/Off Fob (YS3605-UC), Dimmer Fob (YS3606-UC), Siren Fob (YS3607-UC)

- Report buttons as numeric value, report rssi as number, fix multiple events not being reported
- Switch to Preferences vs Commands. Display Perferences based on Fob Model chosen
- \*\*\* IMPORTANT: Since YoLink hub does not report the Fob model, the driver assumes it's a "Flex Fob". After installation, set proper model in the Device's preferences section. \*\*\*

# Finger Device v1.0.5 (YS4908-UC)

- Prevent Service app from waiting on device polling completion
- Updated driver to recognize actions being initiated on the YoLink app

## **Temperature Sensor v2.0.6 (YS8004-UC)**

- Prevent Service app from waiting on device polling completion
- Add temperature history tracking attributes: "highDay", "highestDate", "lowDay", "lowestDate", "highest", "lowest"
- Add commands: "resetDayHighLow", "resetHighLow"

#### Manipulator (Valve) v2.0.6 (YS4909-UC)

- Prevent Service app from waiting on device polling completion
- Set "schedules" attribute to 0 on installation or reset
- Correct weekdays displayed in schedules

## **Lock Device v2.0.3 (YS7606-UC,YUF-02BN)**

- Prevent Service app from waiting on device polling completion
- Add "%" unit to 'battery'

## **Drivers updated to prevent Service app from waiting on device polling completion:**

- vibrationSensor Device v2.0.4
- Thermostat v2.0.3
- Relay v2.0.3
- Smart Outdoor Plug v1.0.4
- Siren v2.0.4
- Plug v2.0.3
- MultiOutlet v2.1.5
- Motion Sensor v2.0.4
- LeakSensor3 v2.0.2

- LeakSensor v2.0.5
- Hub v2.0.3
- Door Sensor v2.0.3
- Dimmer v2.0.3
- Smoke & CO Alarm v2.0.3
- Sprinkler v2.0.3