

Control Hazards BEQ R, R2, L1 IF ID EX M WB 2 cycle bubble
What to do? 1) Flush bosed mechanism

— guess taken er Not Taken. 2) Delayed Branch

ADD R2, R8, R9 ADD R10, R11, R12 BEQ R1, R2, L1

Wol
(Instructions
that does
nothing)

If you commot find independent instructions -> put NOPS

3) Do the composison in ID