
# **Data Analytics Report for Parts Data**

## 1) GParts Part Measures.xlsx

#### **Percentage of Parts with No Dimensions**




## Percentage of Active Parts of total Parts and No\_Dim Parts

Active Parts: 212530; Active Percentage: 91.55% Not Active Parts: 19615; Not Active Percentage: 8.45%

#### **For All Parts**

### For Parts without Dim



Active Parts of No Dimensions: 36947;

Percentage of Active Parts having no Dims: 96.48%

Non-Active Parts of No Dimensions: 1347;

Percentage of non-Active Parts having no Dims: 3.52%

Active Parts with Dimensions: 175583;

Percentage of Active Parts with Dims: 90.58%

Non-Active Parts with Dimensions: 18268;

Percentage of Non-Active Parts with Dimensions: 9.42%