Work Process

Start

- 1. Process is set to Manual.
- 2. Start is ON
- 3. Lid and Base emitter: ON
- 4. Lid and Base conveyor: ON
- 5. Lid and Base at place: FTRIG

Middle

- 1. Base and Lid Clamp: ON (Set Coil)
- 2. Move Z: ON (Set Coil)
 - a. Item Detected

IF False: Move Z: OFF, ERROR (RESet Coil)

(If there is an item , grab item, move back $\, Z \,$, move $\, X \,$, move $\, Z \,$, grab off , move back $\, Z \,$, move back $\, X \,$)

IF True: Grab item: ON (Set Coil)

i. MOVE X, MOVE Z: ON (Set Coil)

ii. Grab: OFF, MOVE Z: OFF (RESet Coil)

iii.

3. Base and Lid Clamp: OFF

END

1.Pos Raise Bases : ON
2. Base Conveyor : ON
3.Part Leaving : FTRIG

4.Pos Raise Bases: OFF

5.Run Conveyor: TOFF, Remove: ON