

NTPC Safety Bulletin

Personal Protective Equipment (PPE) is mandatory in all plant operational areas. Hard hats, safety shoes, and flame-resistant coveralls must be worn at all times.

Hot work permits are required for welding, cutting, or grinding near fuel handling systems. Confined space entry requires gas testing, attendant assignment, and rescue plan approval.

Report all near-miss incidents within 24 hours through the NTPC safety portal. First aid stations are located at each unit control building entrance.