Sensor management

H.I.T.T. · Varsity · 1 sensor per helmet

26 sensors · 24 assigned · 2 spare

+ Register new sensor

Sensors

Search by sensor ID or player

e.g. HT-0142 or Doyle

All | Needs reassignment · 2 | Spare · 2

SENSOR	ASSIGNED TO	STATUS	BATT.
HT-0142	#80 P. Doyle WR · Graduated	Needs reassign	82%
HT-0171	#14 G. Fisher K · No longer playing	Needs reassign	64%
HT-0163	Unassigned In equipment room	Spare	100%
HT-0158	Unassigned In equipment room	Spare	97%
HT-0137	#54 J. Carter LB	Assigned	71%
HT-0151	#22 M. Reyes RB	Assigned	68%
HT-0118	#75 A. Lindqvist OL	Assigned	59%
HT-0129	#7 D. Okafor QB	Assigned	88%
HT-0104	#61 R. Patel OL	Assigned	74%
HT-0145	#33 K. Wallace S	Assigned	80%

EDIT SENSOR

Reassign HT-0142

● Connected Battery 82% Firmware 1.3

1 Release from current player

Currently in helmet of
#80 Patrick Doyle · WR · Sr.

Reason: Graduated

ⓘ P. Doyle's 412 recorded impacts stay on his player record. They do not move with the sensor.


2 Choose new player

Players without a sensor

Search roster

- (●) **#36 Jalen Whitfield** — LB · So. · New helmet issued
- ( ) **#19 Nico Alvarez** — WR · Fr.
- ( ) **#67 Owen Mensah** — OL · Fr.
- ( ) **#2 Trey Ross** — CB · Jr. · Transfer

3 Install and verify



- [ ] Sensor removed from old helmet
- [ ] Mounted at crown of new helmet
- [ ] Test tap registered on dashboard

Run test tap

Retire this sensor instead

HT-0142 → #36 Jalen Whitfield

Cancel | Save reassignment