

What the complete book resolves

Ten findings close 13 previous review-log entries. Three require transcription corrections; six confirm existing readings; one is explained by the book’s own notes. The findings come from cross-referencing all 7,571 structured table records, the end notes, selected original photographs, and Plate 16.

Three corrections applied

Folio	Earlier draft	Verified reading and evidence
43	SH40A1D	SH40AD. The bushing photograph and the matching chain component on 61 agree.
66	SH975C	SH976C. The clip photograph and the bolt-use reference on 31 agree. SH975C remains a separate hose code.
97	First rivet: 1½” long	1⅞” long, ½” diameter. The four rivets match the individual listing on 169.

A repeated component code that is correct

SH599A occurs in both left and right exhaust-manifold assemblies on 122–123. Note (go), page 309, explains that the components are identical and are assembled at 61° to form the noninterchangeable left and right units. This resolves the apparent duplication without changing the historical text.

What “resolved” means here

A confirmed reading is a statement about what the source says. It is not independent verification of a part’s manufactured dimensions. Conflicting printed values, uncertain glyphs and blank source cells are retained. This targeted audit does not replace a fresh, independent proofread of every page.

The updated log has 113 open entries and 99 resolved entries. Thirteen older entries were closed; one newly noticed source discrepancy was added. Several log entries concern general proofreading or layout, so these counts are not counts of individual unreadable characters.

Photographic evidence for the corrections

These are crops of the original photographs, rotated only for reading. No letters or numbers have been reconstructed in the images. Supporting folios remain in sources/.

43 → SH40AD

The individual bushing code; compare the same code in the chain list on 61.

Printed page 43

SH40AD	BUSHING, distributor contact arm dismounting stud mounting
SH978S	BUSHING, drive sprocket chain collar
	BUSHING, engine oil tank (bottom)

Printed page 61

twenty-five SH40AD drive sprocket chain collar BUSHING,

66 → SH976C

Both clips remain without quantities. The bolt-use list on 31 names SH976A and SH976C.

Printed page 66

SH976A	CLIP, water pipe
SH976C	CLIP, water pipe connection

Printed page 31

BOLT, U. S. Std., hexagon head, $\frac{1}{2}$ " x $1\frac{1}{2}$ ", with plain nut and lock washer.
(For clip SH976A (1); clip SH976C (1); strip SH978R (1); housing SH399B (2);
box SH960R (5).)

97 → $1\frac{1}{8}$ "

The first rivet line on 97; the individual entry on 169 explicitly includes four for this frame.

Printed page 97

four — RIVET, button head, $\frac{1}{2}$ " x $1\frac{1}{8}$ ",

Printed page 169

RIVET, button head, $\frac{1}{2}$ " x $1\frac{1}{8}$ ". (For plate M1907 and piece M985 (6); plate M986 and frame M982 (3); plate M1908 and frame M982 (5); plate M1908 and frame M983 (5); strip M1005 and frame M983 (3); plate SH239B (4); plate SH239A (4); transmission frame, assembly (4).)

Existing readings now corroborated

D22921 | 44, 110

D22921 is legible in both the individual flanged-bushing listing on 44 and the component list on 110. Its unusual number sequence is not grounds to change it. A separate disagreement in the adjacent plain-bushing code has been logged.

scoup | 134, 219

The pin description on 134 says screw for scoup spring; the spring listing on 219 also prints scoup. Both photographs support the same spelling. This confirms the literal transcription, without asserting that it is standard terminology.

D26948: No. 6—38 × ¼" | 204, 244

The individual screw entry on 204 and the D1120 switch component on 244 both visibly print No. 6—38. This resolves the reading only; it does not independently validate the manufactured thread or justify changing 38 to 40.

B101965B; 29/64"—28 | 256, 257, 258, 265

The damaged code on 265 is supported by the repeated B101965B component listings on 256–258. The individual union and its component entries agree on 29/64—28 and the C8012/C8013/C8014/C8015/C8016 applications. Existing source punctuation stays unchanged.

606 | 73, 262

The quantity on 262 is visually consistent with 606. Page 73 independently spells out three hundred and three SH607C tubes in each of the front and rear radiator cores: 303 + 303 = 606. This corroborates an existing value, rather than filling a blank.

8209 | 268, 288

Page 268 retains 8209 in the identification column, supported by the clear 8209 manufacturer entry in that row. Plate 16 on 288 independently labels the ring-shaped washer 8209, resolving the damaged identification digit.

Context helps, but does not settle everything

Issue	What the complete book adds	Decision
LQ196A stud 58, 59, 105, 237	The individual listing on 237 joins 58 and 105 in giving 1 9/16". Page 59 gives 1 3/16".	Keep both printed lengths; stronger evidence favors 1 9/16" as the intended specification.
NBIB / NB1B 93, 107, 223	Two later uses identify No. 2 strap fastener NB1B. The glyph on 93 still looks like I.	Record the likely identity; retain the literal uncertain reading on 93.
SH642B spring 138, 219	Both give I.D. 13/16", but O.D. is 1½" on 138 and ½" on 219. Both appear to say 1" thick.	No usable physical dimensions can be inferred safely from this conflict.
Valve-spring collars 67, 79	LQ296A and LQ297A have reversed upper/lower descriptions between the two lists.	Preserve the discrepancy; the notes do not supply an explicit correction.
—Q512B wire 20, 57, 90, 276	Related LQ512A/C/D/E codes and the five-inch wire usage support a likely LQ512B identity.	The missing/ambiguous initial L is not independently repeated. Leave the source reading flagged.
A6951 note (a) 165, 308	The ring entry points to an S hook. Note (d) explains that replacement; no standalone note (a) appears.	Probable erroneous note reference; retain (a), with the explanation recorded separately.

A new discrepancy to retain

The plain tachometer-shaft bushing is D22920 on 44 and D29920 on 110. Both forms are visible. Confirming the neighboring flanged bushing D22921 does not settle which plain-bushing number was intended.

Prices still needing better evidence

The tentative prices on 3, 6, 15, 37, 147, 197, 225, 229 and 245 were not resolved by a sufficient repeated same-item price. Assembly costs and neighboring price patterns are not substitutes for the original digits.