



Air-Cut Referenced Fingerprints: Isolated Process Signatures


*Magnetic field disturbance
from motor currents
(air-cut referenced)*



*Vertical vibration
at workpiece
(air-cut referenced)*



*Y-axis motor
magnetic field
(air-cut referenced)*



*Cutting torque
proxy
(air-cut referenced)*

