

Manufacturer Recall Notice

RECALL

Recall Number	LX-2026-0091
Affected Model	XC21-100
Affected Serial Range	SN-LEN-450000 through SN-LEN-460000

SAFETY HAZARD DESCRIPTION

A wiring defect in the induced draft motor can overheat and pose a fire hazard under continuous high-demand operation.

REMEDY OFFERED

Free in-home inspection and replacement of the induced draft motor wiring harness by an authorized Lennox dealer.

THIS UNIT

Serial No.	SN-LEN-456789	Service address	2847 N 24th St, Phoenix, AZ 85016
------------	---------------	-----------------	-----------------------------------