

FID-10: No Connection to Unit - Hardware Module: ABIL (FSP Subunit Lost / No Connection to Unit)

This document section is exclusively about Fault ID FID-10 occurring in Hardware Module ABIL (FSP Subunit Lost / No Connection to Unit). Applicable SW is 25R3, 26R1, 26R2. Waiting Period is Auto-recovery resets 3 times, then 1-hour waiting period if BBMOD reset required. Use this file when query contains ABIL (FSP Subunit Lost / No Connection to Unit).

Fault ID: FID-10

Hardware Module: ABIL (FSP Subunit Lost / No Connection to Unit)

Applicable SW: 25R3, 26R1, 26R2

Waiting Period: Auto-recovery resets 3 times, then 1-hour waiting period if BBMOD reset required

System Status: No Connection to Unit at ABIL - FSP Subunit Lost

Recovery Steps for ABIL (FSP Subunit Lost / No Connection to Unit):

Step 1 for ABIL (FSP Subunit Lost / No Connection to Unit): Wait for automatic recovery resets (3 times).

Step 2 for ABIL (FSP Subunit Lost / No Connection to Unit): If ABIL not recovered after auto recovery, perform BBMOD power off / power on (with 1-hour waiting period).

Step 3 for ABIL (FSP Subunit Lost / No Connection to Unit): Perform Web-EM site power reset.

Important Transition Note for this Module:

During troubleshooting of FID-10 for this module, if FID-10 turns into FID-1850 / FID-23 / FID-2934 / FID-2935 / FID-2942, it means connectivity to RU is established. Action: Collect RU logs and snapshot at this point for R&D; investigation.

Keywords for retrieval: FID-10, ABIL, BBMOD, FSP Subunit Lost, No Connection to Unit, Web-EM site power reset, FID-1850, FID-23, FID-2934, FID-2935, FID-2942

--- END OF CHUNK FOR MODULE ABIL (FSP Subunit Lost / No Connection to Unit) ---