

FID-10: No Connection to Unit - Hardware Module: AHLOB / AHFII

This document section is exclusively about Fault ID FID-10 occurring in Hardware Module AHLOB / AHFII. Applicable SW is 25R3, 26R1, 26R2. Waiting Period is 45 Minutes + 20 Minutes SFP wait. Use this file when query contains AHLOB / AHFII.

Fault ID: FID-10

Hardware Module: AHLOB / AHFII

Applicable SW: 25R3, 26R1, 26R2

Waiting Period: 45 Minutes + 20 Minutes SFP wait

System Status: No Connection to Unit at AHLOB / AHFII

Recovery Steps for AHLOB / AHFII:

Step 1 for AHLOB / AHFII: Collect Pre and Post Snapshot for AHLOB / AHFII.

Step 2 for AHLOB / AHFII: Check Rx power at BB from the unit.

Step 3 for AHLOB / AHFII: Try SFP procedure and wait minimum 20 minutes.

Step 4 for AHLOB / AHFII: The unit should recover on its own in most cases.

Important Transition Note for this Module:

During troubleshooting of FID-10 for this module, if FID-10 turns into FID-1850 / FID-23 / FID-2934 / FID-2935 / FID-2942, it means connectivity to RU is established. Action: Collect RU logs and snapshot at this point for R&D; investigation.

Keywords for retrieval: FID-10, AHLOB, AHFII, Rx power at BB, SFP procedure, 45 Minutes, FID-1850, FID-23, FID-2934, FID-2935, FID-2942

--- END OF CHUNK FOR MODULE AHLOB / AHFII ---